

# Lexmark Security Advisory:

Revision: 1.3  
Last update: 14 September 2018  
Public Release Date: 27 August 2018

## Summary

Lexmark has identified a buffer overflow vulnerability in some models of multi-function devices handling of color fax jobs.

This issue is not related to CVE-2018-5925 and CVE-2018-5924.

## References

CVE: CVE-2018-15519, CVE-2018-15520

## Details

### CVE-2018-15519

This vulnerability allows an attacker with crafted fax data to attack a Lexmark multifunction device. The vulnerability allows a remote attacker to execute arbitrary code via crafted color fax data.

CVSS v3 Base Score: 9.8 (AV:N/AC:L/PR:N/UI:N/S:U/C:H/I:H/A:H)  
Impact Subscore: 5.9  
Exploitability Score: 3.9

CVSSv3 scores are calculated in accordance with CVSS version 3.0 (<https://www.first.org/cvss/user-guide>)

### CVE-2018-15520

This vulnerability allows an attacker with crafted fax data to attack a Lexmark multifunction device. This vulnerability allows a remote attacker to crash the device, creating a denial of service condition, or possibly to have unspecified other impact via crafted color fax data.

CVSS v3 Base Score: 7.5 (AV:N/AC:L/PR:N/UI:N/S:U/C:N/I:N/A:H)  
Impact Score: 3.6  
Exploitability Score: 3.9

CVSSv3 scores are calculated in accordance with CVSS version 3.0 (<https://www.first.org/cvss/user-guide>)

## Impact

### CVE-2018-15519

Successful exploitation of this vulnerability can also lead to an attacker being able to remotely execute arbitrary code on a device. This condition may continue until the crafted fax data is wiped from the device. For instructions on recovering a device in this state, contact the Lexmark Technical Support Center.

## CVE-2018-15520

Successful exploitation of this vulnerability can lead to an attacker being able to crash a device, resulting in a denial-of-service until the crafted fax data is wiped from the device.

For instructions on recovering a device in this state, contact the Lexmark Technical Support Center.

## Affected Products

Many Lexmark products support Fax, and are affected by this vulnerability when they receive and process color fax jobs. The complete list of affected devices is shown below.

To determine a devices firmware level, select the “**Settings**” > “**Reports**” > ”**Menu Setting Page**” menu item from the operator panel. If the firmware level listed under “**Device Information**” matches any level under “**Affected Releases**”, then you should upgrade to a “**Fixed Release**”.

## CVE-2018-15519

| Lexmark Models                  | Affected Releases          | Fixed Releases          |
|---------------------------------|----------------------------|-------------------------|
| CX310                           | LW70.GM2.P204 and previous | LW70.GM2.P205 and later |
| CX410                           | LW70.GM4.P204 and previous | LW70.GM4.P205 and later |
| CX510, XC2132                   | LW70.GM7.P204 and previous | LW70.GM7.P205 and later |
| MX31x                           | LW70.SB2.P204 and previous | LW70.SB2.P205 and later |
| MX41x, MX51x, XM1145            | LW70.SB4.P204 and previous | LW70.SB4.P205 and later |
| MX61x, XM3150                   | LW70.SB7.P204 and previous | LW70.SB7.P205 and later |
| MX71x, MX81x, XM51xx,<br>XM71xx | LW70.TU.P204 and previous  | LW70.TU.P205 and later  |
| MX91x, XM91x                    | LW70.MG.P204 and previous  | LW70.MG.P205 and later  |
| MX6500                          | LW70.JD.P204 and previous  | LW70.JD.P205 and later  |
| X54x, XS54x                     | LHS60.VK.P671 and previous | LHS60.VK.P672 and later |
| X74x, XS74x                     | LHS60.NY.P671 and previous | LHS60.NY.P672 and later |
| X79x, XS79x                     | LHS60.MR.P671 and previous | LHS60.MR.P672 and later |
| X92x, XS92x                     | LHS60.HK.P671 and previous | LHS60.HK.P672 and later |
| X95x, XS95x                     | LHS60.TQ.P671 and previous | LHS60.TQ.P672 and later |
| 6500                            | LHS60.JR.P671 and previous | LHS60.JR.P672 and later |
| X46x                            | LR.BS.P803 and previous    | LR.BS.P804 and later    |
| X65x                            | LR.MN.P803 and previous    | LR.MN.P804 and later    |
| X73x                            | LR.FL.P803 and previous    | LR.FL.P804 and later    |
| X86x                            | LP.SP.P803 and previous    | LP.SP.P804 and later    |

## CVE-2018-15520

| Lexmark Models  | Affected Releases  | Fixed Releases   |
|---|--|--|
| CX82x, CX860, XC6152, XC8155, XC8160                        | CXTPP.052.024 and previous, plus 052.200 through 052.204 | CXTPP.052.025 and later, excluding 052.200 through 052.204 |
| CX72x, XC41x0   | CXTAT.052.024 and previous, plus 052.200 through 052.204 | CXTAT.052.025 and later, excluding 052.200 through 052.204 |
| CX92x, XC92x5   | CXTMH.052.024 and previous, plus 052.200 through 052.204 | CXTMH.052.025 and later, excluding 052.200 through 052.204 |
| MX321, MB2338   | MXNGM.052.024 and previous, plus 052.200 through 052.204 | MXNGM.052.025 and later, excluding 052.200 through 052.204 |
| MX42x, MX52x, MX622, MB2442, MB2546, MB2650, XM124x, XM3250 | MXTGM.052.024 and previous, plus 052.200 through 052.204 | MXTGM.052.025 and later, excluding 052.200 through 052.204 |
| MX72x, MX82x, MB2770, XM5370, XM7355, XM7370                | MXTGW.052.024 and previous, plus 052.200 through 052.204 | MXTGW.052.025 and later, excluding 052.200 through 052.204 |
| CX421, MC2325, MC2425                                       | CXNZJ.052.024 and previous, plus 052.200 through 052.204 | CXNZJ.052.025 and later, excluding 052.200 through 052.204 |
| CX522, CX62x, MC2535, MC2640, XC2235, XC4240                | CXTZJ.052.024 and previous, plus 052.200 through 052.204 | CXTZJ.052.025 and later, excluding 052.200 through 052.204 |

### **Obtaining Updated Software**

To obtain firmware that resolves this issue, or if you have special code, please contact Lexmark's Technical Support Center at <http://support.lexmark.com> to find your local support center.

### **Workarounds**

Disabling the "Enable Color Fax Receive" feature on a device will block the ability to exploit this vulnerability.

### **Exploitation and Public Announcements**

Lexmark is not aware of any malicious use against Lexmark products of the vulnerability described in this advisory.

### **Status of this Notice:**

THIS DOCUMENT IS PROVIDED ON AN "AS IS" BASIS AND IS PROVIDED WITHOUT ANY EXPRESS OR IMPLIED GUARANTEE OR WARRANTY WHATSOEVER, INCLUDING BUT NOT

LIMITED TO THE WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR USE OR PURPOSE.

## ***Distribution***

This advisory is posted on Lexmark's web site at <http://support.lexmark.com/alerts>  
Future updates to this document will be posted on Lexmark's web site at the same location.

## ***Revision History***

| <b><u>Revision</u></b> | <b><u>Date</u></b>  | <b><u>Reason</u></b>                       |
|------------------------|---------------------|--|
| 1.0                    | 27 - August 2018    | Initial Public Release                     |
| 1.1                    | 28 - August 2018    | Update list of affected models             |
| 1.2                    | 29 - August 2018    | Update list of affected models             |
| 1.3                    | 14 - September 2018 | Update to vector values for CVE-2018-15519 |