Lexmark Security Advisory:

Revision: 1.1

Last update: 13 March 2023 Public Release Date: 10 March 2023

Summary

This input validation vulnerability allows an attacker who has already compromised an affected Lexmark device to escalate privileges.

References

CVE: CVE-2023-26067

ZDI: ZDI-CAN-19766, ZDI-CAN-19774, ZDI-CAN-19470, ZDI-CAN-19731

CWE: CWE-20, CWE-269

Details

A trusted internal component of Lexmark devices has an input validation vulnerability. This vulnerability can be leveraged by an attacker who has already compromised the device to escalate privileges.

NOTE: This vulnerability cannot be used to compromise a device, it can only be used on a device that has already been compromised by another means.

CVSSv3 Base Score 8.0 (AV:N/AC:H/PR:H/UI:N/S:C/C:H/I:H/A:H)

Impact Subscore: 6.0 Exploitability Subscore: 1.3

CVSSv3 scores are calculated in accordance with CVSS version 3.1 (https://www.first.org/cvss/user-guide)

Impact

Successful exploitation of this vulnerability can lead to an attacker being able to remotely execute arbitrary code on a device.

Affected Products

To determine a devices firmware level, select the "Settings"->"Reports"->"Menu Setting Page" menu item from the operator panel. If the firmware level listed under "Device Information" matches any level under "Affected Releases", then upgrade to a "Fixed Release".

Lexmark Models	Affected Releases	Fixed Releases
CX930, CX931, CX942, CX943,	CXTPC.081.232 and previous	CXTPC.081.233 and later
CX944		
XC9325, XC9335, XC9445,	CXTPC.081.232 and previous	CXTPC.081.233 and later
XC9455, XC9465	_	

CS943	CSTPC.081.232 and previous	CSTPC.081.233 and later	
MX432	MXTCT.081.232 and previous	MXTCT.081.233 and later	
XM3142	MXTCT.081.232 and previous	MXTCT.081.233 and later	
MX931	MXTPM.081.232 and previous	MXTPM.081.233 and later	
CX730, CX735	CXTMM.081.232 and previous	CXTMM.081.233 and later	
XC4342, XC4352	CXTMM.081.232 and previous	CXTMM.081.233 and later	
CS730, CS735	CSTMM.081.232 and previous	CSTMM.081.233 and later	
C4342, C4352	CSTMM.081.232 and previous	CSTMM.081.233 and later	
B2236			
MB2236	MSLSG.081.232 and previous	MSLSG.081.233 and later	
	MXLSG.081.232 and previous	MXLSG.081.233 and later	
MS331, MS431, MS439	MSLBD.081.232 and previous	MSLBD 081.233 and later	
M1342	MSLBD.081.232 and previous	MSLBD.081.233 and later	
B3442, B3340	MSLBD.081.232 and previous	MSLBD.081.233 and later	
XM1342	MXLBD.081.232 and previous	MXLBD.081.233 and later	
MX331, MX431	MXLBD.081.232 and previous	MXLBD.081.233 and later	
MB3442	MXLBD.081.232 and previous	MXLBD.081.233 and later	
MS321, MS421, MS521, MS621	MSNGM.081.232 and previous	MSNGM.081.233 and later	
M1242, M1246	MSNGM.081.232 and previous	MSNGM.081.233 and later	
B2338, B2442, B2546, B2650	MSNGM.081.232 and previous	MSNGM.081.233 and later	
MS622	MSTGM.081.232 and previous	MSTGM.081.233 and later	
M3250	MSTGM.081.232 and previous	MSTGM.081.233 and later	
MX321	MXNGM.081.232 and previous	MXNGM.081.233 and later	
MB2338	MXNGM.081.232 and previous	MXNGM.081.233 and later	
MX421, MX521, MX522, MX622	MXTGM.081.232 and previous	MXTGM.081.233 and later	
XM1242, XM1246, XM3250	MXTGM.081.232 and previous	MXTGM.081.233 and later	
MB2442. MB2546, MB2650	MXTGM.081.232 and previous	MXTGM.081.233 and later	
MS725, MS821, MS823, MS825	MSNGW.081.232 and previous	MSNGW.081.233 and later	
B2865	MSNGW.081.232 and previous	MSNGW.081.233 and later	
MS822, MS826	MSTGW.081.232 and previous	MSTGW.081.233 and later	
M5255, M5270	MSTGW.081.232 and previous	MSTGW.081.233 and later	
MX721, MX722, MX725,	MXTGW.081.232 and previous	MXTGW.081.233 and later	
MX822, MX826	WIXTOW.081.232 and previous	WIXTOW.001.233 and later	
XM5365, XM5370, XM7355,	MXTGW.081.232 and previous	MXTGW.081.233 and later	
XM7370	Wixi G W. 001.232 and previous	141741 G W .001.255 and later	
MB2770	MXTGW.081.232 and previous	MXTGW.081.233 and later	
C3426	CSLBN.081.232 and previous	CSLBN.081.233 and later	
CS431, CS439	CSLBN.081.232 and previous	CSLBN.081.233 and later	
CS331	CSLBL.081.232 and previous	CSLBL.081.233 and later	
C3224, C3326	CSLBL.081.232 and previous	CSLBL.081.233 and later	
C2326	CSLBN.081.232 and previous	CSLBN.081.233 and later	
MC3426	CXLBN.081.232 and previous	CXLBN.081.233 and later	
CX431	CXLBN.081.232 and previous	CXLBN.081.233 and later	
XC2326	CXLBN.081.232 and previous	CXLBN.081.233 and later	
MC3426	CXLBN.081.232 and previous	CXLBN.081.233 and later	
MC3224, MC3326	CXLBL.081.232 and previous	CXLBL.081.233 and later	
CX331	CXLBL.081.232 and previous	CXLBL.081.233 and later	
CS622	CSTZJ.081.232 and previous	CSTZJ.081.233 and later	
C2240	CSTZJ.081.232 and previous	CSTZJ.081.233 and later	
CS421, CS521	CSNZJ.081.232 and previous	CSNZJ.081.233 and later	

C2325, C2425, C2535	CSNZJ.081.232 and previous	CSNZJ.081.233 and later
CX522, CX622, CX625	CXTZJ.081.232 and previous	CXTZJ.081.233 and later
XC2235, XC4240	CXTZJ.081.232 and previous	CXTZJ.081.233 and later
MC2535, MC2640	CXTZJ.081.232 and previous	CXTZJ.081.233 and later
CX421	CXNZJ.081.232 and previous	CXNZJ.081.233 and later
MC2325, MC2425	CXNZJ.081.232 and previous	CXNZJ.081.233 and later
CX820, CX825, CX827, CX860	CXTPP.081.232 and previous	CXTPP.081.233 and later
XC6152, XC6153, XC8155,	CXTPP.081.232 and previous	CXTPP.081.233 and later
XC8160, XC8163		
CS820, CS827	CSTPP.081.232 and previous	CSTPP.081.233 and later
C6160	CSTPP.081.232 and previous	CSTPP.081.233 and later
CS720, CS725, CS727, CS728	CSTAT.081.232 and previous	CSTAT.081.233 and later
C4150	CSTAT.081.232 and previous	CSTAT.081.233 and later
CX725, CX727	CXTAT.081.232 and previous	CXTAT.081.233 and later
XC4140, XC4143, XC4150,	CXTAT.081.232 and previous	CXTAT.081.233 and later
XC4153		
CS921, CS923, CS927	CSTMH.081.232 and previous	CSTMH.081.233 and later
C9235	CSTMH.081.232 and previous	CSTMH.081.233 and later
CX920, CX921, CX922, CX923,	CXTMH.081.232 and previous	CXTMH.081.233 and later
CX924		
XC9225, XC9235, XC9245,	CXTMH.081.232 and previous	CXTMH.081.233 and later
XC9255, XC9265		

Obtaining Updated Software

To obtain firmware that resolves this issue or if you have special code, please contact Lexmark's Technical Support Center at http://support.lexmark.com to find your local support center.

Workarounds

Lexmark recommends a firmware update if your device has affected firmware.

Exploitation and Public Announcements

Lexmark is not aware of any malicious use against Lexmark products of the vulnerability described in this advisory.

Lexmark would like to thank the following people working with Trend Micro's Zero Day Initiative (ZDI) for bringing this issue to our attention:

James Horseman Zach Hanley Aleksei Stafeev

David BERARD (@_p0ly_) from @Synacktiv Thomas IMBERT (@masthoon) from @Synacktiv

Jérôme MAMPIANINAZAKASON (@walleza_) from @Synacktiv

Pwn2Own Toronto 2022 DEVCOR team

Status of this Notice:

THIS DOCUMENT IS PROVIDED ON AN "AS IS" BASIS AND IS PROVIDED WITHOUT ANY EXPRESS OR IMPLIED GUARANTEE OR WARRANTY WHATSOEVER, INCLUDING BUT NOT

LIMITED TO THE WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR USE OR PURPOSE. LEXMARK RESERVES THE RIGHT TO CHANGE OR UPDATE THIS DOCUMENT AT ANY TIME.

Distribution

This advisory is posted on Lexmark's web site at http://support.lexmark.com/alerts
Future updates to this document will be posted on Lexmark's web site at the same location.

Revision History

Revision	Date	Reason
1.0	28 February 2023	Initial Public Release
1.1	13 March 2023	Updated Affected Products list