

# Lexmark Security Advisory:

Revision: 0.2  
Last update: 29 Feb 2024  
Public Release Date: 1 Apr 2024

## Summary

A Server-Side Request Forgery (SSRF) vulnerability exists in newer Lexmark devices.

## References

CVE: CVE-2023-50733

CWE: CWE-918, CWE-20

## Details

A Server-Side Request Forgery (SSRF) vulnerability has been identified in the Web Services feature of newer Lexmark devices.

CVSSv3 Base Score 8.6 (AV:N/AC:L/PR:N/UI:N/S:C/C:H/I:N/A:N)  
Impact Subscore: 4.0  
Exploitability Subscore: 3.9

CVSSv3 scores are calculated in accordance with CVSS version 3.1 (<https://www.first.org/cvss/user-guide>)

## Impact

Successful exploitation of this vulnerability can lead to an attacker being able to remotely execute arbitrary code on a device.

## Affected Products

To determine a devices firmware level, select the “Settings”->“Reports”->”Menu Setting Page” menu item from the operator panel. If the firmware level listed under “Device Information” matches any level under “Affected Releases”, then upgrade to a “Fixed Release”.

Lexmark Models	Affected Releases	Fixed Releases
CX930, CX931, CX942, CX943, CX944	CXTPC.230.211 and previous	CXTPC.230.212 and later
XC9325, XC9335, XC9445, XC9455, XC9465	CXTPC.230.211 and previous	CXTPC.230.212 and later
CS943	CSTPC.230.211 and previous	CSTPC.230.212 and later
MX432	MXTCT.230.211 and previous	MXTCT.230.212 and later
XM3142	MXTCT.230.211 and previous	MXTCT.230.212 and later
MX931	MXTPM.230.211 and previous	MXTPM.230.212 and later
CX730, CX735, CX737	CXTMM.230.211 and previous	CXTMM.230.212 and later
XC4342, XC4352	CXTMM.230.211 and previous	CXTMM.230.212 and later
CS730, CS735, CS737	CSTMM.230.211 and previous	CSTMM.230.212 and later
C4342, C4352	CSTMM.230.211 and previous	CSTMM.230.212 and later

B2236	MSLSG.230.211 and previous	MSLSG.230.212 and later
MB2236	MXLSG.230.211 and previous	MXLSG.230.212 and later
MS331, MS431, MS439	MSLBD.230.211 and previous	MSLBD.230.212 and later
M1342	MSLBD.230.211 and previous	MSLBD.230.212 and later
B3442, B3340	MSLBD.230.211 and previous	MSLBD.230.212 and later
XM1342	MXLBD.230.211 and previous	MXLBD.230.212 and later
MX331, MX431	MXLBD.230.211 and previous	MXLBD.230.212 and later
MB3442	MXLBD.230.211 and previous	MXLBD.230.212 and later
MS321, MS421, MS521, MS621	MSNGM.230.211 and previous	MSNGM.230.212 and later
M1242, M1246	MSNGM.230.211 and previous	MSNGM.230.212 and later
B2338, B2442, B2546, B2650	MSNGM.230.211 and previous	MSNGM.230.212 and later
MS622	MSTGM.230.211 and previous	MSTGM.230.212 and later
M3250	MSTGM.230.211 and previous	MSTGM.230.212 and later
MX321	MXNGM.230.211 and previous	MXNGM.230.212 and later
MB2338	MXNGM.230.211 and previous	MXNGM.230.212 and later
MX421, MX521, MX522, MX622	MXTGM.230.211 and previous	MXTGM.230.212 and later
XM1242, XM1246, XM3250	MXTGM.230.211 and previous	MXTGM.230.212 and later
MB2442, MB2546, MB2650	MXTGM.230.211 and previous	MXTGM.230.212 and later
MS725, MS821, MS823, MS825	MSNGW.230.211 and previous	MSNGW.230.212 and later
B2865	MSNGW.230.211 and previous	MSNGW.230.212 and later
MS822, MS826	MSTGW.230.211 and previous	MSTGW.230.212 and later
M5255, M5270	MSTGW.230.211 and previous	MSTGW.230.212 and later
MX721, MX722, MX725, MX822, MX826	MXTGW.230.211 and previous	MXTGW.230.212 and later
XM5365, XM5370, XM7355, XM7370	MXTGW.230.211 and previous	MXTGW.230.212 and later
MB2770	MXTGW.230.211 and previous	MXTGW.230.212 and later
C3426	CSLBN.230.211 and previous	CSLBN.230.212 and later
CS431, CS439	CSLBN.230.211 and previous	CSLBN.230.212 and later
CS331	CSLBL.230.211 and previous	CSLBL.230.212 and later
C3224, C3326	CSLBL.230.211 and previous	CSLBL.230.212 and later
C2326	CSLBN.230.211 and previous	CSLBN.230.212 and later
MC3426	CXLBN.230.211 and previous	CXLBN.230.212 and later
CX431	CXLBN.230.211 and previous	CXLBN.230.212 and later
XC2326	CXLBN.230.211 and previous	CXLBN.230.212 and later
MC3426	CXLBN.230.211 and previous	CXLBN.230.212 and later
MC3224, MC3326	CXLBL.230.211 and previous	CXLBL.230.212 and later
CX331	CXLBL.230.211 and previous	CXLBL.230.212 and later
CS622	CSTZJ.230.211 and previous	CSTZJ.230.212 and later
C2240	CSTZJ.230.211 and previous	CSTZJ.230.212 and later
CS421, CS521	CSNZJ.230.211 and previous	CSNZJ.230.212 and later
C2325, C2425, C2535	CSNZJ.230.211 and previous	CSNZJ.230.212 and later
CX522, CX622, CX625	CXTZJ.230.211 and previous	CXTZJ.230.212 and later

XC2235, XC4240	CXTZJ.230.211 and previous	CXTZJ.230.212 and later
MC2535, MC2640	CXTZJ.230.211 and previous	CXTZJ.230.212 and later
CX421	CXNZJ.230.211 and previous	CXNZJ.230.212 and later
MC2325, MC2425	CXNZJ.230.211 and previous	CXNZJ.230.212 and later
CX820, CX825, CX827, CX860	CXTPP.230.211 and previous	CXTPP.230.212 and later
XC6152, XC6153, XC8155, XC8160, XC8163	CXTPP.230.211 and previous	CXTPP.230.212 and later
CS820, CS827	CSTPP.230.211 and previous	CSTPP.230.212 and later
C6160	CSTPP.230.211 and previous	CSTPP.230.212 and later
CS720, CS725, CS727, CS728	CSTAT.230.211 and previous	CSTAT.230.212 and later
C4150	CSTAT.230.211 and previous	CSTAT.230.212 and later
CX725, CX727	CXTAT.230.211 and previous	CXTAT.230.212 and later
XC4140, XC4143, XC4150, XC4153	CXTAT.230.211 and previous	CXTAT.230.212 and later
CS921, CS923, CS927	CSTMH.230.211 and previous	CSTMH.230.212 and later
C9235	CSTMH.230.211 and previous	CSTMH.230.212 and later
CX920, CX921, CX922, CX923, CX924	CXTMH.230.211 and previous	CXTMH.230.212 and later
XC9225, XC9235, XC9245, XC9255, XC9265	CXTMH.230.211 and previous	CXTMH.230.212 and later
MS531, MS631	MSNSN.222.031 and previous MSNSN.230.001 thru MSNSN.230.211	MSNSN.222.032 thru MSNSN.222.999 MSNSN.230.212 and later
MS632, M3350	MSTSN.222.031 and previous MSTSN.230.001 thru MSTSN.230.211	MSTSN.222.032 thru MSTSN.222.999 MSTSN.230.212 and later
MX532, MX632, XM3350	MXTSN.222.031 and previous MXTSN.230.001 thru MXTSN.230.211	MXTSN.222.032 thru MXTSN.222.999 MXTSN.230.212 and later
CS531, C2335	CSNGV.222.031 and previous CSNGV.230.001 thru CSNGV.230.211	CSNGV.222.032 thru CSNGV.222.999 CSNGV.230.212 and later
CS632	CSTGV.222.031 and previous CSTGV.230.001 thru CSTGV.230.211	CSTGV.222.032 thru CSTGV.222.999 CSTGV.230.212 and later
CX532, CX635, XC2335	CXTGV.222.031 and previous CXTGV.230.001 thru CXTGV.230.211	CXTGV.222.032 thru CXTGV.222.999 CXTGV.230.212 and later

## Obtaining Updated Software

To obtain firmware that resolves this issue or if you have special code, please contact Lexmark's Technical Support Center at <http://support.lexmark.com> to find your local support center.

## Workarounds

Disabling the Web-Services service on the printer (TCP port 65002) blocks the ability to exploit this vulnerability. The port can be blocked by following process: "Settings"->"Network/Ports"- > "TCP/IP"- > "TCP/IP Port Access" then uncheck "TCP 65002 ( WSD Print Service )" and save.

## **Exploitation and Public Announcements**

Lexmark is not aware of any malicious use against Lexmark products of the vulnerability described in this advisory.

Lexmark would like to thank Sina Kheirkhah (@SinSinology) of Summoning Team for bringing this issue to our attention

### **Status of this Notice:**

THIS DOCUMENT IS PROVIDED ON AN "AS IS" BASIS AND IS PROVIDED WITHOUT ANY EXPRESS OR IMPLIED GUARANTEE OR WARRANTY WHATSOEVER, INCLUDING BUT NOT LIMITED TO THE WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR USE OR PURPOSE. LEXMARK RESERVES THE RIGHT TO CHANGE OR UPDATE THIS DOCUMENT AT ANY TIME.

### **Distribution**

This advisory is posted on Lexmark's web site at <http://support.lexmark.com/alerts>  
Future updates to this document will be posted on Lexmark's web site at the same location.

### **Revision History**

<u>Revision</u>	<u>Date</u>	<u>Reason</u>
Draft 0.1	10 Jan 2024	Initial Draft
Draft 0.2	29 Feb 2024	Added affected versions