

Lexmark Security Advisory:

Revision: 1.1
Last update: 22 January 2024
Public Release Date: 29 January 2024

Summary

An input validation vulnerability in the SE Menu allows an attacker to execute arbitrary code.

References

CVE: CVE-2023-50737

ZDI: ZDI-CAN-22520

CWE: CWE-20

Details

The SE menu contains information used by Lexmark to diagnose device errors. A vulnerability in one of the SE menu routines can be leveraged by an attacker to execute arbitrary code.

Lexmark documentation recommends that access to the SE menu be restricted to trusted personnel.

CVSSv3 Base Score 9.1 (AV:N/AC:L/PR:H/UI:N/S:C/C:H/I:H/A:H)
Impact Subscore: 6.0
Exploitability Subscore: 2.3

CVSSv3 scores are calculated in accordance with CVSS version 3.1 (<https://www.first.org/cvss/user-guide>)

Impact

Successful exploitation of this vulnerability can lead to an attacker being able to remotely execute arbitrary code on a device.

Affected Products

To determine a devices firmware level, select the “Settings”->“Reports”->”Menu Setting Page” menu item from the operator panel. If the firmware level listed under “Device Information” matches any level under “Affected Releases”, then upgrade to a “Fixed Release”.

Lexmark Models	Affected Releases	Fixed Releases
CX930, CX931, CX942, CX943, CX944	CXTPC.230.038 and previous CXTPC.230.075 thru CXTPC.230.082 CXTPC.230.200 thru CXTPC.230.202	CXTPC.230.039 thru CXTPC.230.074 CXTPC.230.083 thru CXTPC.230.199 CXTPC.230.203 and later
XC9325, XC9335, XC9445, XC9455, XC9465	CXTPC.230.038 and previous CXTPC.230.075 thru CXTPC.230.082 CXTPC.230.200 thru CXTPC.230.202	CXTPC. 230.039 thru CXTPC.230.074 CXTPC.230.083 thru CXTPC.230.199 CXTPC.230.203 and later
CS943	CSTPC.230.038 and previous CSTPC.230.075 thru CSTPC.230.082 CSTPC.230.200 thru CSTPC.230.202	CSTPC.230.039 thru CSTPC.230.074 CSTPC.230.083 thru CSTPC.230.199 CSTPC.230.203 and later

MX432	MXTCT.230.038 and previous MXTCT.230.075 thru MXTCT.230.082 MXTCT.230.200 thru MXTCT.230.202	MXTCT.230.039 thru MXTCT.230.074 MXTCT.230.083 thru MXTCT.230.199 MXTCT.230.203 and later
XM3142	MXTCT.230.038 and previous MXTCT.230.075 thru MXTCT.230.082 MXTCT.230.200 thru MXTCT.230.202	MXTCT.230.039 thru MXTCT.230.074 MXTCT.230.083 thru MXTCT.230.199 MXTCT.230.203 and later
MX931	MXTPM.230.038 and previous MXTPM.230.075 thru MXTPM.230.082 MXTPM.230.200 thru MXTPM.230.202	MXTPM.230.039 thru MXTPM.230.074 MXTPM.230.083 thru MXTPM.230.199 MXTPM.230.203 and later
CX730, CX735, CX737	CXTMM.230.038 and previous CXTMM.230.075 thru CXTMM.230.082 CXTMM.230.200 thru CXTMM.230.202	CXTMM.230.039 thru CXTMM.230.074 CXTMM.230.083 thru CXTMM.230.199 CXTMM.230.203 and later
XC4342, XC4352	CXTMM.230.038 and previous CXTMM.230.075 thru CXTMM.230.082 CXTMM.230.200 thru CXTMM.230.202	CXTMM.230.039 thru CXTMM.230.074 CXTMM.230.083 thru CXTMM.230.199 CXTMM.230.203 and later
CS730, CS735, CS737	CSTMM.230.038 and previous CSTMM.230.075 thru CSTMM.230.082 CSTMM.230.200 thru CSTMM.230.202	CSTMM.230.039 thru CSTMM.230.074 CSTMM.230.083 thru CSTMM.230.199 CSTMM.230.203 and later
C4342, C4352	CSTMM.230.038 and previous CSTMM.230.075 thru CSTMM.230.082 CSTMM.230.200 thru CSTMM.230.202	CSTMM.230.039 thru CSTMM.230.074 CSTMM.230.083 thru CSTMM.230.199 CSTMM.230.203 and later
B2236	MSLSG.230.038 and previous MSLSG.230.075 thru MSLSG.230.082 MSLSG.230.200 thru MSLSG.230.202	MSLSG.230.039 thru MSLSG.230.074 MSLSG.230.083 thru MSLSG.230.199 MSLSG.230.203 and later
MB2236	MXLSG.230.038 and previous MXLSG.230.075 thru MXLSG.230.082 MXLSG.230.200 thru MXLSG.230.202	MXLSG.230.039 thru MXLSG.230.074 MXLSG.230.083 thru MXLSG.230.199 MXLSG.230.203 and later
MS331, MS431, MS439	MSLBD.230.038 and previous MSLBD.230.075 thru MSLBD.230.082 MSLBD.230.200 thru MSLBD.230.202	MSLBD.230.039 thru MSLBD.230.074 MSLBD.230.083 thru MSLBD.230.199 MSLBD.230.203 and later
M1342	MSLBD.230.038 and previous MSLBD.230.075 thru MSLBD.230.082 MSLBD.230.200 thru MSLBD.230.202	MSLBD.230.039 thru MSLBD.230.074 MSLBD.230.083 thru MSLBD.230.199 MSLBD.230.203 and later
B3442, B3340	MSLBD.230.038 and previous MSLBD.230.075 thru MSLBD.230.082 MSLBD.230.200 thru MSLBD.230.202	MSLBD.230.039 thru MSLBD.230.074 MSLBD.230.083 thru MSLBD.230.199 MSLBD.230.203 and later
XM1342	MXLBD.230.038 and previous MXLBD.230.075 thru MXLBD.230.082 MXLBD.230.200 thru MXLBD.230.202	MXLBD.230.039 thru MXLBD.230.074 MXLBD.230.083 thru MXLBD.230.199 MXLBD.230.203 and later
MX331, MX431	MXLBD.230.038 and previous MXLBD.230.075 thru MXLBD.230.082 MXLBD.230.200 thru MXLBD.230.202	MXLBD.230.039 thru MXLBD.230.074 MXLBD.230.083 thru MXLBD.230.199 MXLBD.230.203 and later
MB3442	MXLBD.230.038 and previous MXLBD.230.075 thru MXLBD.230.082 MXLBD.230.200 thru MXLBD.230.202	MXLBD.230.039 thru MXLBD.230.074 MXLBD.230.083 thru MXLBD.230.199 MXLBD.230.203 and later
MS321, MS421, MS521, MS621	MSNGM.230.038 and previous MSNGM.230.075 thru MSNGM.230.082 MSNGM.230.200 thru MSNGM.230.202	MSNGM.230.039 thru MSNGM.230.074 MSNGM.230.083 thru MSNGM.230.199 MSNGM.230.203 and later
M1242, M1246	MSNGM.230.038 and previous MSNGM.230.075 thru MSNGM.230.082 MSNGM.230.200 thru MSNGM.230.202	MSNGM.230.039 thru MSNGM.230.074 MSNGM.230.083 thru MSNGM.230.199 MSNGM.230.203 and later

B2338, B2442, B2546, B2650	MSNGM.230.038 and previous MSNGM.230.075 thru MSNGM.230.082 MSNGM.230.200 thru MSNGM.230.202	MSNGM.230.039 thru MSNGM.230.074 MSNGM.230.083 thru MSNGM.230.199 MSNGM.230.203 and later
MS622	MSTGM.230.038 and previous MSTGM.230.075 thru MSTGM.230.082 MSTGM.230.200 thru MSTGM.230.202	MSTGM.230.039 thru MSTGM.230.074 MSTGM.230.083 thru MSTGM.230.199 MSTGM.230.203 and later
M3250	MSTGM.230.038 and previous MSTGM.230.075 thru MSTGM.230.082 MSTGM.230.200 thru MSTGM.230.202	MSTGM.230.039 thru MSTGM.230.074 MSTGM.230.083 thru MSTGM.230.199 MSTGM.230.203 and later
MX321	MXNGM.230.038 and previous MXNGM.230.075 thru MXNGM.230.082 MXNGM.230.200 thru MXNGM.230.202	MXNGM.230.039 thru MXNGM.230.074 MXNGM.230.083 thru MXNGM.230.199 MXNGM.230.203 and later
MB2338	MXNGM.230.038 and previous MXNGM.230.075 thru MXNGM.230.082 MXNGM.230.200 thru MXNGM.230.202	MXNGM.230.039 thru MXNGM.230.074 MXNGM.230.083 thru MXNGM.230.199 MXNGM.230.203 and later
MX421, MX521, MX522, MX622	MXTGM.230.038 and previous MXTGM.230.075 thru MXTGM.230.082 MXTGM.230.200 thru MXTGM.230.202	MXTGM.230.039 thru MXTGM.230.074 MXTGM.230.083 thru MXTGM.230.199 MXTGM.230.203 and later
XM1242, XM1246, XM3250	MXTGM.230.038 and previous MXTGM.230.075 thru MXTGM.230.082 MXTGM.230.200 thru MXTGM.230.202	MXTGM.230.039 thru MXTGM.230.074 MXTGM.230.083 thru MXTGM.230.199 MXTGM.230.203 and later
MB2442. MB2546, MB2650	MXTGM.230.038 and previous MXTGM.230.075 thru MXTGM.230.082 MXTGM.230.200 thru MXTGM.230.202	MXTGM.230.039 thru MXTGM.230.074 MXTGM.230.083 thru MXTGM.230.199 MXTGM.230.203 and later
MS725, MS821, MS823, MS825	MSNGW.230.038 and previous MSNGW.230.075 thru MSNGW.230.082 MSNGW.230.200 thru MSNGW.230.202	MSNGW.230.039 thru MSNGW.230.074 MSNGW.230.083 thru MSNGW.230.199 MSNGW.230.203 and later
B2865	MSNGW.230.038 and previous MSNGW.230.075 thru MSNGW.230.082 MSNGW.230.200 thru MSNGW.230.202	MSNGW.230.039 thru MSNGW.230.074 MSNGW.230.083 thru MSNGW.230.199 MSNGW.230.203 and later
MS822, MS826	MSTGW.230.038 and previous MSTGW.230.075 thru MSTGW.230.082 MSTGW.230.200 thru MSTGW.230.202	MSTGW.230.039 thru MSTGW.230.074 MSTGW.230.083 thru MSTGW.230.199 MSTGW.230.203 and later
M5255, M5270	MSTGW.230.038 and previous MSTGW.230.075 thru MSTGW.230.082 MSTGW.230.200 thru MSTGW.230.202	MSTGW.230.039 thru MSTGW.230.074 MSTGW.230.083 thru MSTGW.230.199 MSTGW.230.203 and later
MX721, MX722, MX725, MX822, MX826	MXTGW.230.038 and previous MXTGW.230.075 thru MXTGW.230.082 MXTGW.230.200 thru MXTGW.230.202	MXTGW.230.039 thru MXTGW.230.074 MXTGW.230.083 thru MXTGW.230.199 MXTGW.230.203 and later
XM5365, XM5370, XM7355, XM7370	MXTGW.230.038 and previous MXTGW.230.075 thru MXTGW.230.082 MXTGW.230.200 thru MXTGW.230.202	MXTGW.230.039 thru MXTGW.230.074 MXTGW.230.083 thru MXTGW.230.199 MXTGW.230.203 and later
MB2770	MXTGW.230.038 and previous MXTGW.230.075 thru MXTGW.230.082 MXTGW.230.200 thru MXTGW.230.202	MXTGW.230.039 thru MXTGW.230.074 MXTGW.230.083 thru MXTGW.230.199 MXTGW.230.203 and later
C3426	CSLBN.230.038 and previous CSLBN.230.075 thru CSLBN.230.082 CSLBN.230.200 thru CSLBN.230.202	CSLBN.230.039 thru CSLBN.230.074 CSLBN.230.083 thru CSLBN.230.199 CSLBN.230.203 and later
CS431, CS439	CSLBN.230.038 and previous CSLBN.230.075 thru CSLBN.230.082 CSLBN.230.200 thru CSLBN.230.202	CSLBN.230.039 thru CSLBN.230.074 CSLBN.230.083 thru CSLBN.230.199 CSLBN.230.203 and later

CS331	CSLBL.230.038 and previous CSLBL.230.075 thru CSLBL.230.082 CSLBL.230.200 thru CSLBL.230.202	CSLBL.230.039 thru CSLBL.230.074 CSLBL.230.083 thru CSLBL.230.199 CSLBL.230.203 and later
C3224, C3326	CSLBL.230.038 and previous CSLBL.230.075 thru CSLBL.230.082 CSLBL.230.200 thru CSLBL.230.202	CSLBL.230.039 thru CSLBL.230.074 CSLBL.230.083 thru CSLBL.230.199 CSLBL.230.203 and later
C2326	CSLBN.230.038 and previous CSLBN.230.075 thru CSLBN.230.082 CSLBN.230.200 thru CSLBN.230.202	CSLBN.230.039 thru CSLBN.230.074 CSLBN.230.083 thru CSLBN.230.199 CSLBN.230.203 and later
MC3426	CXLBN.230.038 and previous CXLBN.230.075 thru CXLBN.230.082 CXLBN.230.200 thru CXLBN.230.202	CXLBN.230.039 thru CXLBN.230.074 CXLBN.230.083 thru CXLBN.230.199 CXLBN.230.203 and later
CX431	CXLBN.230.038 and previous CXLBN.230.075 thru CXLBN.230.082 CXLBN.230.200 thru CXLBN.230.202	CXLBN.230.039 thru CXLBN.230.074 CXLBN.230.083 thru CXLBN.230.199 CXLBN.230.203 and later
XC2326	CXLBN.230.038 and previous CXLBN.230.075 thru CXLBN.230.082 CXLBN.230.200 thru CXLBN.230.202	CXLBN.230.039 thru CXLBN.230.074 CXLBN.230.083 thru CXLBN.230.199 CXLBN.230.203 and later
MC3426	CXLBN.230.038 and previous CXLBN.230.075 thru CXLBN.230.082 CXLBN.230.200 thru CXLBN.230.202	CXLBN.230.039 thru CXLBN.230.074 CXLBN.230.083 thru CXLBN.230.199 CXLBN.230.203 and later
MC3224, MC3326	CXLBL.230.038 and previous CXLBL.230.075 thru CXLBL.230.082 CXLBL.230.200 thru CXLBL.230.202	CXLBL.230.039 thru CXLBL.230.074 CXLBL.230.083 thru CXLBL.230.199 CXLBL.230.203 and later
CX331	CXLBL.230.038 and previous CXLBL.230.075 thru CXLBL.230.082 CXLBL.230.200 thru CXLBL.230.202	CXLBL.230.039 thru CXLBL.230.074 CXLBL.230.083 thru CXLBL.230.199 CXLBL.230.203 and later
CS622	CSTZJ.230.038 and previous CSTZJ.230.075 thru CSTZJ.230.082 CSTZJ.230.200 thru CSTZJ.230.202	CSTZJ.230.039 thru CSTZJ.230.074 CSTZJ.230.083 thru CSTZJ.230.199 CSTZJ.230.203 and later
C2240	CSTZJ.230.038 and previous CSTZJ.230.075 thru CSTZJ.230.082 CSTZJ.230.200 thru CSTZJ.230.202	CSTZJ.230.039 thru CSTZJ.230.074 CSTZJ.230.083 thru CSTZJ.230.199 CSTZJ.230.203 and later
CS421, CS521	CSNZJ.230.038 and previous CSNZJ.230.075 thru CSNZJ.230.082 CSNZJ.230.200 thru CSNZJ.230.202	CSNZJ.230.039 thru CSNZJ.230.074 CSNZJ.230.083 thru CSNZJ.230.199 CSNZJ.230.203 and later
C2325, C2425, C2535	CSNZJ.230.038 and previous CSNZJ.230.075 thru CSNZJ.230.082 CSNZJ.230.200 thru CSNZJ.230.202	CSNZJ.230.039 thru CSNZJ.230.074 CSNZJ.230.083 thru CSNZJ.230.199 CSNZJ.230.203 and later
CX522, CX622, CX625	CXTZJ.230.038 and previous CXTZJ.230.075 thru CXTZJ.230.082 CXTZJ.230.200 thru CXTZJ.230.202	CXTZJ.230.039 thru CXTZJ.230.074 CXTZJ.230.083 thru CXTZJ.230.199 CXTZJ.230.203 and later
XC2235, XC4240	CXTZJ.230.038 and previous CXTZJ.230.075 thru CXTZJ.230.082 CXTZJ.230.200 thru CXTZJ.230.202	CXTZJ.230.039 thru CXTZJ.230.074 CXTZJ.230.083 thru CXTZJ.230.199 CXTZJ.230.203 and later
MC2535, MC2640	CXTZJ.230.038 and previous CXTZJ.230.075 thru CXTZJ.230.082 CXTZJ.230.200 thru CXTZJ.230.202	CXTZJ.230.039 thru CXTZJ.230.074 CXTZJ.230.083 thru CXTZJ.230.199 CXTZJ.230.203 and later
CX421	CXNZJ.230.038 and previous CXNZJ.230.075 thru CXNZJ.230.082 CXNZJ.230.200 thru CXNZJ.230.202	CXNZJ.230.039 thru CXNZJ.230.074 CXNZJ.230.083 thru CXNZJ.230.199 CXNZJ.230.203 and later

MC2325, MC2425	CXNZJ.230.038 and previous CXNZJ.230.075 thru CXNZJ.230.082 CXNZJ.230.200 thru CXNZJ.230.202	CXNZJ.230.039 thru CXNZJ.230.074 CXNZJ.230.083 thru CXNZJ.230.199 CXNZJ.230.203 and later
CX820, CX825, CX827, CX860	CXTPP.230.038 and previous CXTPP.230.075 thru CXTPP.230.082 CXTPP.230.200 thru CXTPP.230.202	CXTPP.230.039 thru CXTPP.230.074 CXTPP.230.083 thru CXTPP.230.199 CXTPP.230.203 and later
XC6152, XC6153, XC8155, XC8160, XC8163	CXTPP.230.038 and previous CXTPP.230.075 thru CXTPP.230.082 CXTPP.230.200 thru CXTPP.230.202	CXTPP.230.039 thru CXTPP.230.074 CXTPP.230.083 thru CXTPP.230.199 CXTPP.230.203 and later
CS820, CS827	CSTPP.230.038 and previous CSTPP.230.075 thru CSTPP.230.082 CSTPP.230.200 thru CSTPP.230.202	CSTPP.230.039 thru CSTPP.230.074 CSTPP.230.083 thru CSTPP.230.199 CSTPP.230.203 and later
C6160	CSTPP.230.038 and previous CSTPP.230.075 thru CSTPP.230.082 CSTPP.230.200 thru CSTPP.230.202	CSTPP.230.039 thru CSTPP.230.074 CSTPP.230.083 thru CSTPP.230.199 CSTPP.230.203 and later
CS720, CS725, CS727, CS728	CSTAT.230.038 and previous CSTAT.230.075 thru CSTAT.230.082 CSTAT.230.200 thru CSTAT.230.202	CSTAT.230.039 thru CSTAT.230.074 CSTAT.230.083 thru CSTAT.230.199 CSTAT.230.203 and later
C4150	CSTAT.230.038 and previous CSTAT.230.075 thru CSTAT.230.082 CSTAT.230.200 thru CSTAT.230.202	CSTAT.230.039 thru CSTAT.230.074 CSTAT.230.083 thru CSTAT.230.199 CSTAT.230.203 and later
CX725, CX727	CXTAT.230.038 and previous CXTAT.230.075 thru CXTAT.230.082 CXTAT.230.200 thru CXTAT.230.202	CXTAT.230.039 thru CXTAT.230.074 CXTAT.230.083 thru CXTAT.230.199 CXTAT.230.203 and later
XC4140, XC4143, XC4150, XC4153	CXTAT.230.038 and previous CXTAT.230.075 thru CXTAT.230.082 CXTAT.230.200 thru CXTAT.230.202	CXTAT.230.039 thru CXTAT.230.074 CXTAT.230.083 thru CXTAT.230.199 CXTAT.230.203 and later
CS921, CS923, CS927	CSTMH.230.038 and previous CSTMH.230.075 thru CSTMH.230.082 CSTMH.230.200 thru CSTMH.230.202	CSTMH.230.039 thru CSTMH.230.074 CSTMH.230.083 thru CSTMH.230.199 CSTMH.230.203 and later
C9235	CSTMH.230.038 and previous CSTMH.230.075 thru CSTMH.230.082 CSTMH.230.200 thru CSTMH.230.202	CSTMH.230.039 thru CSTMH.230.074 CSTMH.230.083 thru CSTMH.230.199 CSTMH.230.203 and later
CX920, CX921, CX922, CX923, CX924	CXTMH.230.038 and previous CXTMH.230.075 thru CXTMH.230.082 CXTMH.230.200 thru CXTMH.230.202	CXTMH.230.039 thru CXTMH.230.074 CXTMH.230.083 thru CXTMH.230.199 CXTMH.230.203 and later
XC9225, XC9235, XC9245, XC9255, XC9265	CXTMH.230.038 and previous CXTMH.230.075 thru CXTMH.230.082 CXTMH.230.200 thru CXTMH.230.202	CXTMH.230.039 thru CXTMH.230.074 CXTMH.230.083 thru CXTMH.230.199 CXTMH.230.203 and later
MS531, MS631	MSNSN.222.030 and previous MSNSN.230.001 thru MSNSN.230.038 MSNSN.230.075 thru MSNSN.230.082 MSNSN.230.200 thru MSNSN.230.202	MSNSN.222.031 thru MSNSN.222.999 MSNSN.230.039 thru MSNSN.230.074 MSNSN.230.083 thru MSNSN.230.199 MSNSN.230.203 and later
MS632, M3350	MSTSN.222.030 and previous MSTSN.230.001 thru MSTSN.230.038 MSTSN.230.075 thru MSTSN.230.082 MSTSN.230.200 thru MSTSN.230.202	MSTSN.222.031 thru MSTSN.222.999 MSTSN.230.039 thru MSTSN.230.074 MSTSN.230.083 thru MSTSN.230.199 MSTSN.230.203 and later

MX532, MX632, XM3350	MXTSN.222.030 and previous MXTSN.230.001 thru MXTSN.230.038 MXTSN.230.075 thru MXTSN.230.082 MXTSN.230.200 thru MXTSN.230.202	MXTSN.222.031 thru MXTSN.222.999 MXTSN.230.039 thru MXTSN.230.074 MXTSN.230.083 thru MXTSN.230.199 MXTSN.230.203 and later
CS531, C2335	CSNGV.222.030 and previous CSNGV.230.001 thru CSNGV.230.038 CSNGV.230.075 thru CSNGV.230.082 CSNGV.230.200 thru CSNGV.230.202	CSNGV.222.031 thru CSNGV.222.999 CSNGV.230.039 thru CSNGV.230.074 CSNGV.230.083 thru CSNGV.230.199 CSNGV.230.203 and later
CS632	CSTGV.222.030 and previous CSTGV.230.001 thru CSTGV.230.038 CSTGV.230.075 thru CSTGV.230.082 CSTGV.230.200 thru CSTGV.230.202	CSTGV.222.031 thru CSTGV.222.999 CSTGV.230.039 thru CSTGV.230.074 CSTGV.230.083 thru CSTGV.230.199 CSTGV.230.203 and later
CX532, CX635, XC2335	CXTGV.222.030 and previous CXTGV.230.001 thru CXTGV.230.038 CXTGV.230.075 thru CXTGV.230.082 CXTGV.230.200 thru CXTGV.230.202	CXTGV.222.031 thru CXTGV.222.999 CXTGV.230.039 thru CXTGV.230.074 CXTGV.230.083 thru CXTGV.230.199 CXTGV.230.203 and later

Obtaining Updated Software

To obtain firmware that resolves this issue or if you have special code, please contact Lexmark's Technical Support Center at <http://support.lexmark.com> to find your local support center.

Workarounds

To block access to the SE menu from untrusted users go to **Settings->Security->Login Methods->Public->Manage Permissions->Administrative Menus** and uncheck "SE Menu"

Lexmark recommends a firmware update if your device has affected firmware.

Exploitation and Public Announcements

Lexmark is not aware of any malicious use against Lexmark products of the vulnerability described in this advisory.

Lexmark would like to thank Sina Kheirkhah of Summoning Team working with Trend Micro's Zero Day Initiative (ZDI) for bringing this issue to our attention:

Status of this Notice:

THIS DOCUMENT IS PROVIDED ON AN "AS IS" BASIS AND IS PROVIDED WITHOUT ANY EXPRESS OR IMPLIED GUARANTEE OR WARRANTY WHATSOEVER, INCLUDING BUT NOT LIMITED TO THE WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR USE OR PURPOSE. LEXMARK RESERVES THE RIGHT TO CHANGE OR UPDATE THIS DOCUMENT AT ANY TIME.

Distribution

This advisory is posted on Lexmark's web site at <http://support.lexmark.com/alerts>
Future updates to this document will be posted on Lexmark's web site at the same location.

Revision History

<u>Revision</u>	<u>Date</u>	<u>Reason</u>
1.0	05 January 2024	Initial Public Release
1.1	22 January 2024	Fixed typos in Affected Products