

Lexmark Security Advisory:

Revision: 1.0
Last update: 05 January 2024
Public Release Date: 19 January 2024

Summary

A vulnerability has been identified in the PostScript interpreter in various Lexmark devices.

References

CVE: CVE-2023-50736

ZDI: ZDI-CAN-22445

CWE: CWE-131

Details

A memory corruption vulnerability has been identified in PostScript interpreter in various Lexmark devices. The vulnerability can be leveraged by an attacker to execute arbitrary code.

CVSSv3 Base Score 9.0 (AV:N/AC:H/PR:N/UI:N/S:C/C:H/I:H/A:H)
Impact Subscore: 6.0
Exploitability Subscore: 2.2

CVSSv3 scores are calculated in accordance with CVSS version 3.1 (<https://www.first.org/cvss/user-guide>)

Impact

Successful exploitation of this vulnerability can lead to an attacker being able to remotely execute arbitrary code on a device.

Affected Products

To determine a devices firmware level, select the “Settings”->“Reports”->”Menu Setting Page” menu item from the operator panel. If the firmware level listed under “Device Information” matches any level under “Affected Releases”, then upgrade to a “Fixed Release”.

Lexmark Models	Affected Releases	Fixed Releases
CX930, CX931, CX942, CX943, CX944	CXTPC.230.041 and previous CXTPC.230.075 thru CXTPC.230.081 CXTPC.230.200 thru CXTPC.230.203	CXTPC.230.042 thru CXTPC.230.074 CXTPC.230.082 thru CXTPC.230.199 CXTPC.230.204 and later
XC9325, XC9335, XC9445, XC9455, XC9465	CXTPC.230.041 and previous CXTPC.230.075 thru CXTPC.230.081 CXTPC.230.200 thru CXTPC.230.203	CXTPC. 230.042 thru CXTPC.230.074 CXTPC.230.082 thru CXTPC.230.199 CXTPC.230.204 and later

CS943	CSTPC.230.041 and previous CSTPC.230.075 thru CSTPC.230.081 CSTPC.230.200 thru CSTPC.230.203	CSTPC.230.042 thru CSTPC.230.074 CSTPC.230.082 thru CSTPC.230.199 CSTPC.230.204 and later
MX432	MXTCT.230.041 and previous MXTCT.230.075 thru MXTCT.230.081 MXTCT.230.200 thru MXTCT.230.203	MXTCT.230.042 thru MXTCT.230.074 MXTCT.230.082 thru MXTCT.230.199 MXTCT.230.204 and later
XM3142	MXTCT.230.041 and previous MXTCT.230.075 thru MXTCT.230.081 MXTCT.230.200 thru MXTCT.230.203	MXTCT.230.042 thru MXTCT.230.074 MXTCT.230.082 thru MXTCT.230.199 MXTCT.230.204 and later
MX931	MXTPM.230.041 and previous MXTPM.230.075 thru MXTPM.230.081 MXTPM.230.200 thru MXTPM.230.203	MXTPM.230.042 thru MXTPM.230.074 MXTPM.230.082 thru MXTPM.230.199 MXTPM.230.204 and later
CX730, CX735, CX737	CXTMM.230.041 and previous CXTMM.230.075 thru CXTMM.230.081 CXTMM.230.200 thru CXTMM.230.203	CXTMM.230.042 thru CXTMM.230.074 CXTMM.230.082 thru CXTMM.230.199 CXTMM.230.204 and later
XC4342, XC4352	CXTMM.230.041 and previous CXTMM.230.075 thru CXTMM.230.081 CXTMM.230.200 thru CXTMM.230.203	CXTMM.230.042 thru CXTMM.230.074 CXTMM.230.082 thru CXTMM.230.199 CXTMM.230.204 and later
CS730, CS735, CS737	CSTMM.230.041 and previous CSTMM.230.075 thru CSTMM.230.081 CSTMM.230.200 thru CSTMM.230.203	CSTMM.230.042 thru CSTMM.230.074 CSTMM.230.082 thru CSTMM.230.199 CSTMM.230.204 and later
C4342, C4352	CSTMM.230.041 and previous CSTMM.230.075 thru CSTMM.230.081 CSTMM.230.200 thru CSTMM.230.203	CSTMM.230.042 thru CSTMM.230.074 CSTMM.230.082 thru CSTMM.230.199 CSTMM.230.204 and later
B2236	MSLSG.230.041 and previous MSLSG.230.075 thru MSLSG.230.081 MSLSG.230.200 thru MSLSG.230.203	MSLSG.230.042 thru MSLSG.230.074 MSLSG.230.082 thru MSLSG.230.199 MSLSG.230.204 and later
MB2236	MXLSG.230.041 and previous MXLSG.230.075 thru MXLSG.230.081 MXLSG.230.200 thru MXLSG.230.203	MXLSG.230.042 thru MXLSG.230.074 MXLSG.230.082 thru MXLSG.230.199 MXLSG.230.204 and later
MS331, MS431, MS439	MSLBD.230.041 and previous MSLBD.230.075 thru MSLBD.230.081 MSLBD.230.200 thru MSLBD.230.203	MSLBD.230.042 thru MSLBD.230.074 MSLBD.230.082 thru MSLBD.230.199 MSLBD.230.204 and later
M1342	MSLBD.230.041 and previous MSLBD.230.075 thru MSLBD.230.081 MSLBD.230.200 thru MSLBD.230.203	MSLBD.230.042 thru MSLBD.230.074 MSLBD.230.082 thru MSLBD.230.199 MSLBD.230.204 and later
B3442, B3340	MSLBD.230.041 and previous MSLBD.230.075 thru MSLBD.230.081 MSLBD.230.200 thru MSLBD.230.203	MSLBD.230.042 thru MSLBD.230.074 MSLBD.230.082 thru MSLBD.230.199 MSLBD.230.204 and later
XM1342	MXLBD.230.041 and previous MXLBD.230.075 thru MXLBD.230.081 MXLBD.230.200 thru MXLBD.230.203	MXLBD.230.042 thru MXLBD.230.074 MXLBD.230.082 thru MXLBD.230.199 MXLBD.230.204 and later
MX331, MX431	MXLBD.230.041 and previous MXLBD.230.075 thru MXLBD.230.081 MXLBD.230.200 thru MXLBD.230.203	MXLBD.230.042 thru MXLBD.230.074 MXLBD.230.082 thru MXLBD.230.199 MXLBD.230.204 and later
MB3442	MXLBD.230.041 and previous MXLBD.230.075 thru MXLBD.230.081 MXLBD.230.200 thru MXLBD.230.203	MXLBD.230.042 thru MXLBD.230.074 MXLBD.230.082 thru MXLBD.230.199 MXLBD.230.204 and later
MS321, MS421, MS521, MS621	MSNGM.230.041 and previous MSNGM.230.075 thru MSNGM.230.081 MSNGM.230.200 thru MSNGM.230.203	MSNGM.230.042 thru MSNGM.230.074 MSNGM.230.082 thru MSNGM.230.199 MSNGM.230.204 and later

M1242, M1246	MSNGM.230.041 and previous MSNGM.230.075 thru MSNGM.230.081 MSNGM.230.200 thru MSNGM.230.203	MSNGM.230.042 thru MSNGM.230.074 MSNGM.230.082 thru MSNGM.230.199 MSNGM.230.204 and later
B2338, B2442, B2546, B2650	MSNGM.230.041 and previous MSNGM.230.075 thru MSNGM.230.081 MSNGM.230.200 thru MSNGM.230.203	MSNGM.230.042 thru MSNGM.230.074 MSNGM.230.082 thru MSNGM.230.199 MSNGM.230.204 and later
MS622	MSTGM.230.041 and previous MSTGM.230.075 thru MSTGM.230.081 MSTGM.230.200 thru MSTGM.230.203	MSTGM.230.042 thru MSTGM.230.074 MSTGM.230.082 thru MSTGM.230.199 MSTGM.230.204 and later
M3250	MSTGM.230.041 and previous MSTGM.230.075 thru MSTGM.230.081 MSTGM.230.200 thru MSTGM.230.203	MSTGM.230.042 thru MSTGM.230.074 MSTGM.230.082 thru MSTGM.230.199 MSTGM.230.204 and later
MX321	MXNGM.230.041 and previous MXNGM.230.075 thru MXNGM.230.081 MXNGM.230.200 thru MXNGM.230.203	MXNGM.230.042 thru MXNGM.230.074 MXNGM.230.082 thru MXNGM.230.199 MXNGM.230.204 and later
MB2338	MXNGM.230.041 and previous MXNGM.230.075 thru MXNGM.230.081 MXNGM.230.200 thru MXNGM.230.203	MXNGM.230.042 thru MXNGM.230.074 MXNGM.230.082 thru MXNGM.230.199 MXNGM.230.204 and later
MX421, MX521, MX522, MX622	MXTGM.230.041 and previous MXTGM.230.075 thru MXTGM.230.081 MXTGM.230.200 thru MXTGM.230.203	MXTGM.230.042 thru MXTGM.230.074 MXTGM.230.082 thru MXTGM.230.199 MXTGM.230.204 and later
XM1242, XM1246, XM3250	MXTGM.230.041 and previous MXTGM.230.075 thru MXTGM.230.081 MXTGM.230.200 thru MXTGM.230.203	MXTGM.230.042 thru MXTGM.230.074 MXTGM.230.082 thru MXTGM.230.199 MXTGM.230.204 and later
MB2442. MB2546, MB2650	MXTGM.230.041 and previous MXTGM.230.075 thru MXTGM.230.081 MXTGM.230.200 thru MXTGM.230.203	MXTGM.230.042 thru MXTGM.230.074 MXTGM.230.082 thru MXTGM.230.199 MXTGM.230.204 and later
MS725, MS821, MS823, MS825	MSNGW.230.041 and previous MSNGW.230.075 thru MSNGW.230.081 MSNGW.230.200 thru MSNGW.230.203	MSNGW.230.042 thru MSNGW.230.074 MSNGW.230.082 thru MSNGW.230.199 MSNGW.230.204 and later
B2865	MSNGW.230.041 and previous MSNGW.230.075 thru MSNGW.230.081 MSNGW.230.200 thru MSNGW.230.203	MSNGW.230.042 thru MSNGW.230.074 MSNGW.230.082 thru MSNGW.230.199 MSNGW.230.204 and later
MS822, MS826	MSTGW.230.041 and previous MSTGW.230.075 thru MSTGW.230.081 MSTGW.230.200 thru MSTGW.230.203	MSTGW.230.042 thru MSTGW.230.074 MSTGW.230.082 thru MSTGW.230.199 MSTGW.230.204 and later
M5255, M5270	MSTGW.230.041 and previous MSTGW.230.075 thru MSTGW.230.081 MSTGW.230.200 thru MSTGW.230.203	MSTGW.230.042 thru MSTGW.230.074 MSTGW.230.082 thru MSTGW.230.199 MSTGW.230.204 and later
MX721, MX722, MX725, MX822, MX826	MXTGW.230.041 and previous MXTGW.230.075 thru MXTGW.230.081 MXTGW.230.200 thru MXTGW.230.203	MXTGW.230.042 thru MXTGW.230.074 MXTGW.230.082 thru MXTGW.230.199 MXTGW.230.204 and later
XM5365, XM5370, XM7355, XM7370	MXTGW.230.041 and previous MXTGW.230.075 thru MXTGW.230.081 MXTGW.230.200 thru MXTGW.230.203	MXTGW.230.042 thru MXTGW.230.074 MXTGW.230.082 thru MXTGW.230.199 MXTGW.230.204 and later
MB2770	MXTGW.230.041 and previous MXTGW.230.075 thru MXTGW.230.081 MXTGW.230.200 thru MXTGW.230.203	MXTGW.230.042 thru MXTGW.230.074 MXTGW.230.082 thru MXTGW.230.199 MXTGW.230.204 and later
C3426	CSLBN.230.041 and previous CSLBN.230.075 thru CSLBN.230.081 CSLBN.230.200 thru CSLBN.230.203	CSLBN.230.042 thru CSLBN.230.074 CSLBN.230.082 thru CSLBN.230.199 CSLBN.230.204 and later

CS431, CS439	CSLBN.230.041 and previous CSLBN.230.075 thru CSLBN.230.081 CSLBN.230.200 thru CSLBN.230.203	CSLBN.230.042 thru CSLBN.230.074 CSLBN.230.082 thru CSLBN.230.199 CSLBN.230.204 and later
CS331	CSLBL.230.041 and previous CSLBL.230.075 thru CSLBL.230.081 CSLBL.230.200 thru CSLBL.230.203	CSLBL.230.042 thru CSLBL.230.074 CSLBL.230.082 thru CSLBL.230.199 CSLBL.230.204 and later
C3224, C3326	CSLBL.230.041 and previous CSLBL.230.075 thru CSLBL.230.081 CSLBL.230.200 thru CSLBL.230.203	CSLBL.230.042 thru CSLBL.230.074 CSLBL.230.082 thru CSLBL.230.199 CSLBL.230.204 and later
C2326	CSLBN.230.041 and previous CSLBN.230.075 thru CSLBN.230.081 CSLBN.230.200 thru CSLBN.230.203	CSLBN.230.042 thru CSLBN.230.074 CSLBN.230.082 thru CSLBN.230.199 CSLBN.230.204 and later
MC3426	CXLBN.230.041 and previous CXLBN.230.075 thru CXLBN.230.081 CXLBN.230.200 thru CXLBN.230.203	CXLBN.230.042 thru CXLBN.230.074 CXLBN.230.082 thru CXLBN.230.199 CXLBN.230.204 and later
CX431	CXLBN.230.041 and previous CXLBN.230.075 thru CXLBN.230.081 CXLBN.230.200 thru CXLBN.230.203	CXLBN.230.042 thru CXLBN.230.074 CXLBN.230.082 thru CXLBN.230.199 CXLBN.230.204 and later
XC2326	CXLBN.230.041 and previous CXLBN.230.075 thru CXLBN.230.081 CXLBN.230.200 thru CXLBN.230.203	CXLBN.230.042 thru CXLBN.230.074 CXLBN.230.082 thru CXLBN.230.199 CXLBN.230.204 and later
MC3426	CXLBN.230.041 and previous CXLBN.230.075 thru CXLBN.230.081 CXLBN.230.200 thru CXLBN.230.203	CXLBN.230.042 thru CXLBN.230.074 CXLBN.230.082 thru CXLBN.230.199 CXLBN.230.204 and later
MC3224, MC3326	CXLBL.230.041 and previous CXLBL.230.075 thru CXLBL.230.081 CXLBL.230.200 thru CXLBL.230.203	CXLBL.230.042 thru CXLBL.230.074 CXLBL.230.082 thru CXLBL.230.199 CXLBL.230.204 and later
CX331	CXLBL.230.041 and previous CXLBL.230.075 thru CXLBL.230.081 CXLBL.230.200 thru CXLBL.230.203	CXLBL.230.042 thru CXLBL.230.074 CXLBL.230.082 thru CXLBL.230.199 CXLBL.230.204 and later
CS622	CSTZJ.230.041 and previous CSTZJ.230.075 thru CSTZJ.230.081 CSTZJ.230.200 thru CSTZJ.230.203	CSTZJ.230.042 thru CSNZJ.230.074 CSNZJ.230.082 thru CSNZJ.230.199 CSNZJ.230.204 and later
C2240	CSTZJ.230.041 and previous CSTZJ.230.075 thru CSTZJ.230.081 CSTZJ.230.200 thru CSTZJ.230.203	CSTZJ.230.042 thru CSNZJ.230.074 CSNZJ.230.082 thru CSNZJ.230.199 CSNZJ.230.204 and later
CS421, CS521	CSNZJ.230.041 and previous CSNZJ.230.075 thru CSNZJ.230.081 CSNZJ.230.200 thru CSNZJ.230.203	CSNZJ.230.042 thru CSNZJ.230.074 CSNZJ.230.082 thru CSNZJ.230.199 CSNZJ.230.204 and later
C2325, C2425, C2535	CSNZJ.230.041 and previous CSNZJ.230.075 thru CSNZJ.230.081 CSNZJ.230.200 thru CSNZJ.230.203	CSNZJ.230.042 thru CSNZJ.230.074 CSNZJ.230.082 thru CSNZJ.230.199 CSNZJ.230.204 and later
CX522, CX622, CX625	CXTZJ.230.041 and previous CXTZJ.230.075 thru CXTZJ.230.081 CXTZJ.230.200 thru CXTZJ.230.203	CXTZJ.230.042 thru CXTZJ.230.074 CXTZJ.230.082 thru CXTZJ.230.199 CXTZJ.230.204 and later
XC2235, XC4240	CXTZJ.230.041 and previous CXTZJ.230.075 thru CXTZJ.230.081 CXTZJ.230.200 thru CXTZJ.230.203	CXTZJ.230.042 thru CXTZJ.230.074 CXTZJ.230.082 thru CXTZJ.230.199 CXTZJ.230.204 and later
MC2535, MC2640	CXTZJ.230.041 and previous CXTZJ.230.075 thru CXTZJ.230.081 CXTZJ.230.200 thru CXTZJ.230.203	CXTZJ.230.042 thru CXTZJ.230.074 CXTZJ.230.082 thru CXTZJ.230.199 CXTZJ.230.204 and later

CX421	CXNZJ.230.041 and previous CXNZJ.230.075 thru CXNZJ.230.081 CXNZJ.230.200 thru CXNZJ.230.203	CXNZJ.230.042 thru CXNZJ.230.074 CXNZJ.230.082 thru CXNZJ.230.199 CXNZJ.230.204 and later
MC2325, MC2425	CXNZJ.230.041 and previous CXNZJ.230.075 thru CXNZJ.230.081 CXNZJ.230.200 thru CXNZJ.230.203	CXNZJ.230.042 thru CXTTP.230.074 CXTTP.230.082 thru CXTTP.230.199 CXTTP.230.204 and later
CX820, CX825, CX827, CX860	CXTTP.230.041 and previous CXTTP.230.075 thru CXTTP.230.081 CXTTP.230.200 thru CXTTP.230.203	CXTTP.230.042 thru CXTPC.230.074 CXTPC.230.082 thru CXTPC.230.199 CXTPC.230.204 and later
XC6152, XC6153, XC8155, XC8160, XC8163	CXTTP.230.041 and previous CXTTP.230.075 thru CXTTP.230.081 CXTTP.230.200 thru CXTTP.230.203	CXTTP.230.042 thru CXTTP.230.074 CXTTP.230.082 thru CXTTP.230.199 CXTTP.230.204 and later
CS820, CS827	CSTPP.230.041 and previous CSTPP.230.075 thru CSTPP.230.081 CSTPP.230.200 thru CSTPP.230.203	CSTPP.230.042 thru CSTPP.230.074 CSTPP.230.082 thru CSTPP.230.199 CSTPP.230.204 and later
C6160	CSTPP.230.041 and previous CSTPP.230.075 thru CSTPP.230.081 CSTPP.230.200 thru CSTPP.230.203	CSTPP.230.042 thru CSTPP.230.074 CSTPP.230.082 thru CSTPP.230.199 CSTPP.230.204 and later
CS720, CS725, CS727, CS728	CSTAT.230.041 and previous CSTAT.230.075 thru CSTAT.230.081 CSTAT.230.200 thru CSTAT.230.203	CSTAT.230.042 thru CSTAT.230.074 CSTAT.230.082 thru CSTAT.230.199 CSTAT.230.204 and later
C4150	CSTAT.230.041 and previous CSTAT.230.075 thru CSTAT.230.081 CSTAT.230.200 thru CSTAT.230.203	CSTAT.230.042 thru CSTAT.230.074 CSTAT.230.082 thru CSTAT.230.199 CSTAT.230.204 and later
CX725, CX727	CXTAT.230.041 and previous CXTAT.230.075 thru CXTAT.230.081 CXTAT.230.200 thru CXTAT.230.203	CXTAT.230.042 thru CXTAT.230.074 CXTAT.230.082 thru CXTAT.230.199 CXTAT.230.204 and later
XC4140, XC4143, XC4150, XC4153	CXTAT.230.041 and previous CXTAT.230.075 thru CXTAT.230.081 CXTAT.230.200 thru CXTAT.230.203	CXTAT.230.042 thru CXTAT.230.074 CXTAT.230.082 thru CXTAT.230.199 CXTAT.230.204 and later
CS921, CS923, CS927	CSTMH.230.041 and previous CSTMH.230.075 thru CSTMH.230.081 CSTMH.230.200 thru CSTMH.230.203	CSTMH.230.042 thru CSTMH.230.074 CSTMH.230.082 thru CSTMH.230.199 CSTMH.230.204 and later
C9235	CSTMH.230.041 and previous CSTMH.230.075 thru CSTMH.230.081 CSTMH.230.200 thru CSTMH.230.203	CSTMH.230.042 thru CSTMH.230.074 CSTMH.230.082 thru CSTMH.230.199 CSTMH.230.204 and later
CX920, CX921, CX922, CX923, CX924	CXTMH.230.041 and previous CXTMH.230.075 thru CXTMH.230.081 CXTMH.230.200 thru CXTMH.230.203	CXTMH.230.042 thru CXTMH.230.074 CXTMH.230.082 thru CXTMH.230.199 CXTMH.230.204 and later
XC9225, XC9235, XC9245, XC9255, XC9265	CXTMH.230.041 and previous CXTMH.230.075 thru CXTMH.230.081 CXTMH.230.200 thru CXTMH.230.203	CXTMH.230.042 thru CXTMH.230.074 CXTMH.230.082 thru CXTMH.230.199 CXTMH.230.204 and later
MS531, MS631	MSNSN.222.030 and previous MSNSN.230.001 thru MSNSN.230.041 MSNSN.230.075 thru MSNSN.230.081 MSNSN.230.200 thru MSNSN.230.203	MSNSN.222.031 thru MSNSN.222.999 MSNSN.230.042 thru MSNSN.230.074 MSNSN.230.082 thru MSNSN.230.199 MSNSN.230.204 and later
MS632, M3350	MSTSN.222.030 and previous MSTSN.230.001 thru MSTSN.230.041 MSTSN.230.075 thru MSTSN.230.081 MSTSN.230.200 thru MSTSN.230.203	MSTSN.222.031 thru MSTSN.222.999 MSTSN.230.042 thru MSTSN.230.074 MSTSN.230.082 thru MSTSN.230.199 MSTSN.230.204 and later

MX532, MX632, XM3350	MXTSN.222.030 and previous MXTSN.230.001 thru MXTSN.230.041 MXTSN.230.075 thru MXTSN.230.081 MXTSN.230.200 thru MXTSN.230.203	MXTSN.222.031 thru MXTSN.222.999 MXTSN.230.042 thru MXTSN.230.074 MXTSN.230.082 thru MXTSN.230.199 MXTSN.230.204 and later
CS531, C2335	CSNGV.222.030 and previous CSNGV.230.001 thru CSNGV.230.041 CSNGV.230.075 thru CSNGV.230.081 CSNGV.230.200 thru CSNGV.230.203	CSNGV.222.031 thru CSNGV.222.999 CSNGV.230.042 thru CSNGV.230.074 CSNGV.230.082 thru CSNGV.230.199 CSNGV.230.204 and later
CS632	CSTGV.222.030 and previous CSTGV.230.001 thru CSTGV.230.041 CSTGV.230.075 thru CSTGV.230.081 CSTGV.230.200 thru CSTGV.230.203	CSTGV.222.031 thru CSTGV.222.999 CSTGV.230.042 thru CSTGV.230.074 CSTGV.230.082 thru CSTGV.230.199 CSTGV.230.204 and later
CX532, CX635, XC2335	CXTGV.222.030 and previous CXTGV.230.001 thru CXTGV.230.041 CXTGV.230.075 thru CXTGV.230.081 CXTGV.230.200 thru CXTGV.230.203	CXTGV.222.031 thru CXTGV.222.999 CXTGV.230.042 thru CXTGV.230.074 CXTGV.230.082 thru CXTGV.230.199 CXTGV.230.204 and later
MS315, MS415, MS417	LW90.TL2.P205 and previous	LW90.TL2.P206 and later
MS510, MS517, MS610dn, MS617	LW90.PR2.P205 and previous	LW90.PR2.P206 and later
M1140+, M1145, M3150dn	LW90.PR2.P205 and previous	LW90.PR2.P206 and later
MS610de, M3150de	LW90.PR4.P205 and previous	LW90.PR4.P206 and later
MX410, MX417, MX510, MX511, MX517	LW90.SB4.P205 and previous	LW90.SB4.P206 and later
XM1140, XM1145	LW90.SB4.P205 and previous	LW90.SB4.P206 and later
MX610, MX611, MX617	LW90.SB7.P205 and previous	LW90.SB7.P206 and later
XM3150	LW90.SB7.P205 and previous	LW90.SB7.P206 and later
MS710, MS711, MS810dn, MS811, MS812dn, MS817, MS818	LW90.DN2.P205 and previous	LW90.DN2.P206 and later
M5163dn	LW90.DN2.P205 and previous	LW90.DN2.P206 and later
MS810de	LW90.DN4.P205 and previous	LW90.DN4.P206 and later
M5155, M5163de	LW90.DN4.P205 and previous	LW90.DN4.P206 and later
MS812de	LW90.DN7.P205 and previous	LW90.DN7.P206 and later
M5170	LW90.DN7.P205 and previous	LW90.DN7.P206 and later
MX710, MX711, MX717, MX718, MX810, MX811, MX812	LW90.TU.P205 and previous	LW90.TU.P206 and later
XM5163, XM5170, XM5263, XM5270, XM7155, XM7163, XM7170, XM7263, XM7270	LW90.TU.P205 and previous	LW90.TU.P206 and later
MS911	LW90.SA.P205 and previous	LW90.SA.P206 and later

MX910, MX911, MX912	LW90.MG.P205 and previous	LW90.MG.P206 and later
XM9145, XM9155, XM9165	LW90.MG.P205 and previous	LW90.MG.P206 and later
MX6500e	LW90.JD.P205 and previous	LW90.JD.P206 and later
CS510, CS517	LW90.VY4.P205 and previous	LW90.VY4.P206 and later
C2132	LW90.VY4.P205 and previous	LW90.VY4.P206 and later
CX410, CX417	LW90.GM4.P205 and previous	LW90.GM4.P206 and later
XC2130	LW90.GM4.P205 and previous	LW90.GM4.P206 and later
CX510, CX517	LW90.GM7.P205 and previous	LW90.GM7.P206 and later
XC2132	LW90.GM7.P205 and previous	LW90.GM7.P206 and later
MS310, MS312, MS317, MS410	LW80.PRL.P249 and previous	LW80.PRL.P250 and later
M1140	LW80.PRL.P249 and previous	LW80.PRL.P250 and later
MX310, MX317	LW80.SB2.P249 and previous	LW80.SB2.P250 and later
XM1135	LW80.SB2.P249 and previous	LW80.SB2.P250 and later
CS310, CS317	LW80.VYL.P249 and previous	LW80.VYL.P250 and later
CS410, CS417	LW80.VY2.P249 and previous	LW80.VY2.P250 and later
CX310, CX317	LW80.GM2.P249 and previous	LW80.GM2.P250 and later
C746	LHS60.CM2.P763 and previous	LHS60.CM2.P764 and later
C748, CS748	LHS60.CM4.P763 and previous	LHS60.CM4.P764 and later
C792, CS796	LHS60.HC.P763 and previous	LHS60.HC.P764 and later
C925	LHS60.HV.P763 and previous	LHS60.HV.P764 and later
C950	LHS60.TP.P763 and previous	LHS60.TP.P764 and later
X548, XS548	LHS60.VK.P763 and previous	LHS60.VK.P764 and later
X746, X748, XS748	LHS60.NY.P763 and previous	LHS60.NY.P764 and later
X792, XS795, XS796, XS798	LHS60.MR.P763 and previous	LHS60.MR.P764 and later
X925, XS925	LHS60.HK.P763 and previous	LHS60.HK.P764 and later
X950, X952, X954, XS950, XS955	LHS60.TQ.P763 and previous	LHS60.TQ.P764 and later
6500e	LHS60.JR.P763 and previous	LHS60.JR.P764 and later

Obtaining Updated Software

To obtain firmware that resolves this issue or if you have special code, please contact Lexmark's Technical Support Center at <http://support.lexmark.com> to find your local support center.

Workarounds

Lexmark recommends a firmware update if your device has affected firmware.

Exploitation and Public Announcements

Lexmark is not aware of any malicious use against Lexmark products of the vulnerability described in this advisory.

Lexmark would like to thank Chris Anastasio working with Trend Micro's Zero Day Initiative (ZDI) for bringing this issue to our attention:

Status of this Notice:

THIS DOCUMENT IS PROVIDED ON AN "AS IS" BASIS AND IS PROVIDED WITHOUT ANY EXPRESS OR IMPLIED GUARANTEE OR WARRANTY WHATSOEVER, INCLUDING BUT NOT LIMITED TO THE WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR USE OR PURPOSE. LEXMARK RESERVES THE RIGHT TO CHANGE OR UPDATE THIS DOCUMENT AT ANY TIME.

Distribution

This advisory is posted on Lexmark's web site at <http://support.lexmark.com/alerts>
Future updates to this document will be posted on Lexmark's web site at the same location.

Revision History

<u>Revision</u>	<u>Date</u>	<u>Reason</u>
1.0	05 January 2024	Initial Public Release