

# Lexmark Security Advisory:

Revision: 1.1  
Last update: 22 January 2024  
Public Release Date: 29 January 2024

## Summary

A vulnerability has been identified in the PostScript interpreter in various Lexmark devices.

## References

CVE: CVE-2023-50735

ZDI: ZDI-CAN-22443

CWE: CWE-465

## Details

A heap corruption vulnerability has been identified in PostScript interpreter in various Lexmark devices. The vulnerability can be leveraged by an attacker to execute arbitrary code.

CVSSv3 Base Score 9.0 (AV:N/AC:H/PR:N/UI:N/S:C/C:H/I:H/A:H)  
Impact Subscore: 6.0  
Exploitability Subscore: 2.2

CVSSv3 scores are calculated in accordance with CVSS version 3.1 (<https://www.first.org/cvss/user-guide>)

## Impact

Successful exploitation of this vulnerability can lead to an attacker being able to remotely execute arbitrary code on a device.

## Affected Products

To determine a devices firmware level, select the “Settings”->“Reports”->”Menu Setting Page” menu item from the operator panel. If the firmware level listed under “Device Information” matches any level under “Affected Releases”, then upgrade to a “Fixed Release”.

Lexmark Models	Affected Releases	Fixed Releases
CX930, CX931, CX942, CX943, CX944	CXTPC.230.041 and previous CXTPC.230.075 thru CXTPC.230.078 CXTPC.230.200 thru CXTPC.230.202	CXTPC.230.042 thru CXTPC.230.074 CXTPC.230.079 thru CXTPC.230.199 CXTPC.230.203 and later
XC9325, XC9335, XC9445, XC9455, XC9465	CXTPC.230.041 and previous CXTPC.230.075 thru CXTPC.230.078 CXTPC.230.200 thru CXTPC.230.202	CXTPC. 230.042 thru CXTPC.230.074 CXTPC.230.079 thru CXTPC.230.199 CXTPC.230.203 and later

CS943	CSTPC.230.041 and previous CSTPC.230.075 thru CSTPC.230.078 CSTPC.230.200 thru CSTPC.230.202	CSTPC.230.042 thru CSTPC.230.074 CSTPC.230.079 thru CSTPC.230.199 CSTPC.230.203 and later
MX432	MXTCT.230.041 and previous MXTCT.230.075 thru MXTCT.230.078 MXTCT.230.200 thru MXTCT.230.202	MXTCT.230.042 thru MXTCT.230.074 MXTCT.230.079 thru MXTCT.230.199 MXTCT.230.203 and later
XM3142	MXTCT.230.041 and previous MXTCT.230.075 thru MXTCT.230.078 MXTCT.230.200 thru MXTCT.230.202	MXTCT.230.042 thru MXTCT.230.074 MXTCT.230.079 thru MXTCT.230.199 MXTCT.230.203 and later
MX931	MXTPM.230.041 and previous MXTPM.230.075 thru MXTPM.230.078 MXTPM.230.200 thru MXTPM.230.202	MXTPM.230.042 thru MXTPM.230.074 MXTPM.230.079 thru MXTPM.230.199 MXTPM.230.203 and later
CX730, CX735, CX737	CXTMM.230.041 and previous CXTMM.230.075 thru CXTMM.230.078 CXTMM.230.200 thru CXTMM.230.202	CXTMM.230.042 thru CXTMM.230.074 CXTMM.230.079 thru CXTMM.230.199 CXTMM.230.203 and later
XC4342, XC4352	CXTMM.230.041 and previous CXTMM.230.075 thru CXTMM.230.078 CXTMM.230.200 thru CXTMM.230.202	CXTMM.230.042 thru CXTMM.230.074 CXTMM.230.079 thru CXTMM.230.199 CXTMM.230.203 and later
CS730, CS735, CS737	CSTMM.230.041 and previous CSTMM.230.075 thru CSTMM.230.078 CSTMM.230.200 thru CSTMM.230.202	CSTMM.230.042 thru CSTMM.230.074 CSTMM.230.079 thru CSTMM.230.199 CSTMM.230.203 and later
C4342, C4352	CSTMM.230.041 and previous CSTMM.230.075 thru CSTMM.230.078 CSTMM.230.200 thru CSTMM.230.202	CSTMM.230.042 thru CSTMM.230.074 CSTMM.230.079 thru CSTMM.230.199 CSTMM.230.203 and later
B2236	MSLSG.230.041 and previous MSLSG.230.075 thru MSLSG.230.078 MSLSG.230.200 thru MSLSG.230.202	MSLSG.230.042 thru MSLSG.230.074 MSLSG.230.079 thru MSLSG.230.199 MSLSG.230.203 and later
MB2236	MXLSG.230.041 and previous MXLSG.230.075 thru MXLSG.230.078 MXLSG.230.200 thru MXLSG.230.202	MXLSG.230.042 thru MXLSG.230.074 MXLSG.230.079 thru MXLSG.230.199 MXLSG.230.203 and later
MS331, MS431, MS439	MSLBD.230.041 and previous MSLBD.230.075 thru MSLBD.230.078 MSLBD.230.200 thru MSLBD.230.202	MSLBD.230.042 thru MSLBD.230.074 MSLBD.230.079 thru MSLBD.230.199 MSLBD.230.203 and later
M1342	MSLBD.230.041 and previous MSLBD.230.075 thru MSLBD.230.078 MSLBD.230.200 thru MSLBD.230.202	MSLBD.230.042 thru MSLBD.230.074 MSLBD.230.079 thru MSLBD.230.199 MSLBD.230.203 and later
B3442, B3340	MSLBD.230.041 and previous MSLBD.230.075 thru MSLBD.230.078 MSLBD.230.200 thru MSLBD.230.202	MSLBD.230.042 thru MSLBD.230.074 MSLBD.230.079 thru MSLBD.230.199 MSLBD.230.203 and later
XM1342	MXLBD.230.041 and previous MXLBD.230.075 thru MXLBD.230.078 MXLBD.230.200 thru MXLBD.230.202	MXLBD.230.042 thru MXLBD.230.074 MXLBD.230.079 thru MXLBD.230.199 MXLBD.230.203 and later
MX331, MX431	MXLBD.230.041 and previous MXLBD.230.075 thru MXLBD.230.078 MXLBD.230.200 thru MXLBD.230.202	MXLBD.230.042 thru MXLBD.230.074 MXLBD.230.079 thru MXLBD.230.199 MXLBD.230.203 and later
MB3442	MXLBD.230.041 and previous MXLBD.230.075 thru MXLBD.230.078 MXLBD.230.200 thru MXLBD.230.202	MXLBD.230.042 thru MXLBD.230.074 MXLBD.230.079 thru MXLBD.230.199 MXLBD.230.203 and later
MS321, MS421, MS521, MS621	MSNGM.230.041 and previous MSNGM.230.075 thru MSNGM.230.078 MSNGM.230.200 thru MSNGM.230.202	MSNGM.230.042 thru MSNGM.230.074 MSNGM.230.079 thru MSNGM.230.199 MSNGM.230.203 and later

M1242, M1246	MSNGM.230.041 and previous MSNGM.230.075 thru MSNGM.230.078 MSNGM.230.200 thru MSNGM.230.202	MSNGM.230.042 thru MSNGM.230.074 MSNGM.230.079 thru MSNGM.230.199 MSNGM.230.203 and later
B2338, B2442, B2546, B2650	MSNGM.230.041 and previous MSNGM.230.075 thru MSNGM.230.078 MSNGM.230.200 thru MSNGM.230.202	MSNGM.230.042 thru MSNGM.230.074 MSNGM.230.079 thru MSNGM.230.199 MSNGM.230.203 and later
MS622	MSTGM.230.041 and previous MSTGM.230.075 thru MSTGM.230.078 MSTGM.230.200 thru MSTGM.230.202	MSTGM.230.042 thru MSTGM.230.074 MSTGM.230.079 thru MSTGM.230.199 MSTGM.230.203 and later
M3250	MSTGM.230.041 and previous MSTGM.230.075 thru MSTGM.230.078 MSTGM.230.200 thru MSTGM.230.202	MSTGM.230.042 thru MSTGM.230.074 MSTGM.230.079 thru MSTGM.230.199 MSTGM.230.203 and later
MX321	MXNGM.230.041 and previous MXNGM.230.075 thru MXNGM.230.078 MXNGM.230.200 thru MXNGM.230.202	MXNGM.230.042 thru MXNGM.230.074 MXNGM.230.079 thru MXNGM.230.199 MXNGM.230.203 and later
MB2338	MXNGM.230.041 and previous MXNGM.230.075 thru MXNGM.230.078 MXNGM.230.200 thru MXNGM.230.202	MXNGM.230.042 thru MXNGM.230.074 MXNGM.230.079 thru MXNGM.230.199 MXNGM.230.203 and later
MX421, MX521, MX522, MX622	MXTGM.230.041 and previous MXTGM.230.075 thru MXTGM.230.078 MXTGM.230.200 thru MXTGM.230.202	MXTGM.230.042 thru MXTGM.230.074 MXTGM.230.079 thru MXTGM.230.199 MXTGM.230.203 and later
XM1242, XM1246, XM3250	MXTGM.230.041 and previous MXTGM.230.075 thru MXTGM.230.078 MXTGM.230.200 thru MXTGM.230.202	MXTGM.230.042 thru MXTGM.230.074 MXTGM.230.079 thru MXTGM.230.199 MXTGM.230.203 and later
MB2442. MB2546, MB2650	MXTGM.230.041 and previous MXTGM.230.075 thru MXTGM.230.078 MXTGM.230.200 thru MXTGM.230.202	MXTGM.230.042 thru MXTGM.230.074 MXTGM.230.079 thru MXTGM.230.199 MXTGM.230.203 and later
MS725, MS821, MS823, MS825	MSNGW.230.041 and previous MSNGW.230.075 thru MSNGW.230.078 MSNGW.230.200 thru MSNGW.230.202	MSNGW.230.042 thru MSNGW.230.074 MSNGW.230.079 thru MSNGW.230.199 MSNGW.230.203 and later
B2865	MSNGW.230.041 and previous MSNGW.230.075 thru MSNGW.230.078 MSNGW.230.200 thru MSNGW.230.202	MSNGW.230.042 thru MSNGW.230.074 MSNGW.230.079 thru MSNGW.230.199 MSNGW.230.203 and later
MS822, MS826	MSTGW.230.041 and previous MSTGW.230.075 thru MSTGW.230.078 MSTGW.230.200 thru MSTGW.230.202	MSTGW.230.042 thru MSTGW.230.074 MSTGW.230.079 thru MSTGW.230.199 MSTGW.230.203 and later
M5255, M5270	MSTGW.230.041 and previous MSTGW.230.075 thru MSTGW.230.078 MSTGW.230.200 thru MSTGW.230.202	MSTGW.230.042 thru MSTGW.230.074 MSTGW.230.079 thru MSTGW.230.199 MSTGW.230.203 and later
MX721, MX722, MX725, MX822, MX826	MXTGW.230.041 and previous MXTGW.230.075 thru MXTGW.230.078 MXTGW.230.200 thru MXTGW.230.202	MXTGW.230.042 thru MXTGW.230.074 MXTGW.230.079 thru MXTGW.230.199 MXTGW.230.203 and later
XM5365, XM5370, XM7355, XM7370	MXTGW.230.041 and previous MXTGW.230.075 thru MXTGW.230.078 MXTGW.230.200 thru MXTGW.230.202	MXTGW.230.042 thru MXTGW.230.074 MXTGW.230.079 thru MXTGW.230.199 MXTGW.230.203 and later
MB2770	MXTGW.230.041 and previous MXTGW.230.075 thru MXTGW.230.078 MXTGW.230.200 thru MXTGW.230.202	MXTGW.230.042 thru MXTGW.230.074 MXTGW.230.079 thru MXTGW.230.199 MXTGW.230.203 and later
C3426	CSLBN.230.041 and previous CSLBN.230.075 thru CSLBN.230.078 CSLBN.230.200 thru CSLBN.230.202	CSLBN.230.042 thru CSLBN.230.074 CSLBN.230.079 thru CSLBN.230.199 CSLBN.230.203 and later

CS431, CS439	CSLBN.230.041 and previous CSLBN.230.075 thru CSLBN.230.078 CSLBN.230.200 thru CSLBN.230.202	CSLBN.230.042 thru CSLBN.230.074 CSLBN.230.079 thru CSLBN.230.199 CSLBN.230.203 and later
CS331	CSLBL.230.041 and previous CSLBL.230.075 thru CSLBL.230.078 CSLBL.230.200 thru CSLBL.230.202	CSLBL.230.042 thru CSLBL.230.074 CSLBL.230.079 thru CSLBL.230.199 CSLBL.230.203 and later
C3224, C3326	CSLBL.230.041 and previous CSLBL.230.075 thru CSLBL.230.078 CSLBL.230.200 thru CSLBL.230.202	CSLBL.230.042 thru CSLBL.230.074 CSLBL.230.079 thru CSLBL.230.199 CSLBL.230.203 and later
C2326	CSLBN.230.041 and previous CSLBN.230.075 thru CSLBN.230.078 CSLBN.230.200 thru CSLBN.230.202	CSLBN.230.042 thru CSLBN.230.074 CSLBN.230.079 thru CSLBN.230.199 CSLBN.230.203 and later
MC3426	CXLBN.230.041 and previous CXLBN.230.075 thru CXLBN.230.078 CXLBN.230.200 thru CXLBN.230.202	CXLBN.230.042 thru CXLBN.230.074 CXLBN.230.079 thru CXLBN.230.199 CXLBN.230.203 and later
CX431	CXLBN.230.041 and previous CXLBN.230.075 thru CXLBN.230.078 CXLBN.230.200 thru CXLBN.230.202	CXLBN.230.042 thru CXLBN.230.074 CXLBN.230.079 thru CXLBN.230.199 CXLBN.230.203 and later
XC2326	CXLBN.230.041 and previous CXLBN.230.075 thru CXLBN.230.078 CXLBN.230.200 thru CXLBN.230.202	CXLBN.230.042 thru CXLBN.230.074 CXLBN.230.079 thru CXLBN.230.199 CXLBN.230.203 and later
MC3426	CXLBN.230.041 and previous CXLBN.230.075 thru CXLBN.230.078 CXLBN.230.200 thru CXLBN.230.202	CXLBN.230.042 thru CXLBN.230.074 CXLBN.230.079 thru CXLBN.230.199 CXLBN.230.203 and later
MC3224, MC3326	CXLBL.230.041 and previous CXLBL.230.075 thru CXLBL.230.078 CXLBL.230.200 thru CXLBL.230.202	CXLBL.230.042 thru CXLBL.230.074 CXLBL.230.079 thru CXLBL.230.199 CXLBL.230.203 and later
CX331	CXLBL.230.041 and previous CXLBL.230.075 thru CXLBL.230.078 CXLBL.230.200 thru CXLBL.230.202	CXLBL.230.042 thru CXLBL.230.074 CXLBL.230.079 thru CXLBL.230.199 CXLBL.230.203 and later
CS622	CSTZJ.230.041 and previous CSTZJ.230.075 thru CSTZJ.230.078 CSTZJ.230.200 thru CSTZJ.230.202	CSTZJ.230.042 thru CSTZJ.230.074 CSTZJ.230.079 thru CSTZJ.230.199 CSTZJ.230.203 and later
C2240	CSTZJ.230.041 and previous CSTZJ.230.075 thru CSTZJ.230.078 CSTZJ.230.200 thru CSTZJ.230.202	CSTZJ.230.042 thru CSTZJ.230.074 CSTZJ.230.079 thru CSTZJ.230.199 CSTZJ.230.203 and later
CS421, CS521	CSNZJ.230.041 and previous CSNZJ.230.075 thru CSNZJ.230.078 CSNZJ.230.200 thru CSNZJ.230.202	CSNZJ.230.042 thru CSNZJ.230.074 CSNZJ.230.079 thru CSNZJ.230.199 CSNZJ.230.203 and later
C2325, C2425, C2535	CSNZJ.230.041 and previous CSNZJ.230.075 thru CSNZJ.230.078 CSNZJ.230.200 thru CSNZJ.230.202	CSNZJ.230.042 thru CSNZJ.230.074 CSNZJ.230.079 thru CSNZJ.230.199 CSNZJ.230.203 and later
CX522, CX622, CX625	CXTZJ.230.041 and previous CXTZJ.230.075 thru CXTZJ.230.078 CXTZJ.230.200 thru CXTZJ.230.202	CXTZJ.230.042 thru CXTZJ.230.074 CXTZJ.230.079 thru CXTZJ.230.199 CXTZJ.230.203 and later
XC2235, XC4240	CXTZJ.230.041 and previous CXTZJ.230.075 thru CXTZJ.230.078 CXTZJ.230.200 thru CXTZJ.230.202	CXTZJ.230.042 thru CXTZJ.230.074 CXTZJ.230.079 thru CXTZJ.230.199 CXTZJ.230.203 and later
MC2535, MC2640	CXTZJ.230.041 and previous CXTZJ.230.075 thru CXTZJ.230.078 CXTZJ.230.200 thru CXTZJ.230.202	CXTZJ.230.042 thru CXTZJ.230.074 CXTZJ.230.079 thru CXTZJ.230.199 CXTZJ.230.203 and later

CX421	CXNZJ.230.041 and previous CXNZJ.230.075 thru CXNZJ.230.078 CXNZJ.230.200 thru CXNZJ.230.202	CXNZJ.230.042 thru CXNZJ.230.074 CXNZJ.230.079 thru CXNZJ.230.199 CXNZJ.230.203 and later
MC2325, MC2425	CXNZJ.230.041 and previous CXNZJ.230.075 thru CXNZJ.230.078 CXNZJ.230.200 thru CXNZJ.230.202	CXNZJ.230.042 thru CXNZJ.230.074 CXNZJ.230.079 thru CXNZJ.230.199 CXNZJ.230.203 and later
CX820, CX825, CX827, CX860	CXTPP.230.041 and previous CXTPP.230.075 thru CXTPP.230.078 CXTPP.230.200 thru CXTPP.230.202	CXTPP.230.042 thru CXTPC.230.074 CXTPP.230.079 thru CXTPP.230.199 CXTPP.230.203 and later
XC6152, XC6153, XC8155, XC8160, XC8163	CXTPP.230.041 and previous CXTPP.230.075 thru CXTPP.230.078 CXTPP.230.200 thru CXTPP.230.202	CXTPP.230.042 thru CXTPP.230.074 CXTPP.230.079 thru CXTPP.230.199 CXTPP.230.203 and later
CS820, CS827	CSTPP.230.041 and previous CSTPP.230.075 thru CSTPP.230.078 CSTPP.230.200 thru CSTPP.230.202	CSTPP.230.042 thru CSTPP.230.074 CSTPP.230.079 thru CSTPP.230.199 CSTPP.230.203 and later
C6160	CSTPP.230.041 and previous CSTPP.230.075 thru CSTPP.230.078 CSTPP.230.200 thru CSTPP.230.202	CSTPP.230.042 thru CSTPP.230.074 CSTPP.230.079 thru CSTPP.230.199 CSTPP.230.203 and later
CS720, CS725, CS727, CS728	CSTAT.230.041 and previous CSTAT.230.075 thru CSTAT.230.078 CSTAT.230.200 thru CSTAT.230.202	CSTAT.230.042 thru CSTAT.230.074 CSTAT.230.079 thru CSTAT.230.199 CSTAT.230.203 and later
C4150	CSTAT.230.041 and previous CSTAT.230.075 thru CSTAT.230.078 CSTAT.230.200 thru CSTAT.230.202	CSTAT.230.042 thru CSTAT.230.074 CSTAT.230.079 thru CSTAT.230.199 CSTAT.230.203 and later
CX725, CX727	CXTAT.230.041 and previous CXTAT.230.075 thru CXTAT.230.078 CXTAT.230.200 thru CXTAT.230.202	CXTAT.230.042 thru CXTAT.230.074 CXTAT.230.079 thru CXTAT.230.199 CXTAT.230.203 and later
XC4140, XC4143, XC4150, XC4153	CXTAT.230.041 and previous CXTAT.230.075 thru CXTAT.230.078 CXTAT.230.200 thru CXTAT.230.202	CXTAT.230.042 thru CXTAT.230.074 CXTAT.230.079 thru CXTAT.230.199 CXTAT.230.203 and later
CS921, CS923, CS927	CSTMH.230.041 and previous CSTMH.230.075 thru CSTMH.230.078 CSTMH.230.200 thru CSTMH.230.202	CSTMH.230.042 thru CSTMH.230.074 CSTMH.230.079 thru CSTMH.230.199 CSTMH.230.203 and later
C9235	CSTMH.230.041 and previous CSTMH.230.075 thru CSTMH.230.078 CSTMH.230.200 thru CSTMH.230.202	CSTMH.230.042 thru CSTMH.230.074 CSTMH.230.079 thru CSTMH.230.199 CSTMH.230.203 and later
CX920, CX921, CX922, CX923, CX924	CXTMH.230.041 and previous CXTMH.230.075 thru CXTMH.230.078 CXTMH.230.200 thru CXTMH.230.202	CXTMH.230.042 thru CXTMH.230.074 CXTMH.230.079 thru CXTMH.230.199 CXTMH.230.203 and later
XC9225, XC9235, XC9245, XC9255, XC9265	CXTMH.230.041 and previous CXTMH.230.075 thru CXTMH.230.078 CXTMH.230.200 thru CXTMH.230.202	CXTMH.230.042 thru CXTMH.230.074 CXTMH.230.079 thru CXTMH.230.199 CXTMH.230.203 and later
MS531, MS631	MSNSN.222.030 and previous MSNSN.230.001 thru MSNSN.230.041 MSNSN.230.075 thru MSNSN.230.078 MSNSN.230.200 thru MSNSN.230.202	MSNSN.222.031 thru MSNSN.222.999 MSNSN.230.042 thru MSNSN.230.074 MSNSN.230.079 thru MSNSN.230.199 MSNSN.230.203 and later
MS632, M3350	MSTSN.222.030 and previous MSTSN.230.001 thru MSTSN.230.041 MSTSN.230.075 thru MSTSN.230.078 MSTSN.230.200 thru MSTSN.230.202	MSTSN.222.031 thru MSTSN.222.999 MSTSN.230.042 thru MSTSN.230.074 MSTSN.230.079 thru MSTSN.230.199 MSTSN.230.203 and later

MX532, MX632, XM3350	MXTSN.222.030 and previous MXTSN.230.001 thru MXTSN.230.041 MXTSN.230.075 thru MXTSN.230.078 MXTSN.230.200 thru MXTSN.230.202	MXTSN.222.031 thru MXTSN.222.999 MXTSN.230.042 thru MXTSN.230.074 MXTSN.230.079 thru MXTSN.230.199 MXTSN.230.203 and later
CS531, C2335	CSNGV.222.030 and previous CSNGV.230.001 thru CSNGV.230.041 CSNGV.230.075 thru CSNGV.230.078 CSNGV.230.200 thru CSNGV.230.202	CSNGV.222.031 thru CSNGV.222.999 CSNGV.230.042 thru CSNGV.230.074 CSNGV.230.079 thru CSNGV.230.199 CSNGV.230.203 and later
CS632	CSTGV.222.030 and previous CSTGV.230.001 thru CSTGV.230.041 CSTGV.230.075 thru CSTGV.230.078 CSTGV.230.200 thru CSTGV.230.202	CSTGV.222.031 thru CSTGV.222.999 CSTGV.230.042 thru CSTGV.230.074 CSTGV.230.079 thru CSTGV.230.199 CSTGV.230.203 and later
CX532, CX635, XC2335	CXTGV.222.030 and previous CXTGV.230.001 thru CXTGV.230.041 CXTGV.230.075 thru CXTGV.230.078 CXTGV.230.200 thru CXTGV.230.202	CXTGV.222.031 thru CXTGV.222.999 CXTGV.230.042 thru CXTGV.230.074 CXTGV.230.079 thru CXTGV.230.199 CXTGV.230.203 and later
MS315, MS415, MS417	LW90.TL2.P205 and previous	LW90.TL2.P206 and later
MS510, MS517, MS610dn, MS617	LW90.PR2.P205 and previous	LW90.PR2.P206 and later
M1140+, M1145, M3150dn	LW90.PR2.P205 and previous	LW90.PR2.P206 and later
MS610de, M3150de	LW90.PR4.P205 and previous	LW90.PR4.P206 and later
MX410, MX417, MX510, MX511, MX517	LW90.SB4.P205 and previous	LW90.SB4.P206 and later
XM1140, XM1145	LW90.SB4.P205 and previous	LW90.SB4.P206 and later
MX610, MX611, MX617	LW90.SB7.P205 and previous	LW90.SB7.P206 and later
XM3150	LW90.SB7.P205 and previous	LW90.SB7.P206 and later
MS710, MS711, MS810dn, MS811, MS812dn, MS817, MS818	LW90.DN2.P205 and previous	LW90.DN2.P206 and later
M5163dn	LW90.DN2.P205 and previous	LW90.DN2.P206 and later
MS810de	LW90.DN4.P205 and previous	LW90.DN4.P206 and later
M5155, M5163de	LW90.DN4.P205 and previous	LW90.DN4.P206 and later
MS812de	LW90.DN7.P205 and previous	LW90.DN7.P206 and later
M5170	LW90.DN7.P205 and previous	LW90.DN7.P206 and later
MX710, MX711, MX717, MX718, MX810, MX811, MX812	LW90.TU.P205 and previous	LW90.TU.P206 and later
XM5163, XM5170, XM5263, XM5270, XM7155, XM7163, XM7170, XM7263, XM7270	LW90.TU.P205 and previous	LW90.TU.P206 and later
MS911	LW90.SA.P205 and previous	LW90.SA.P206 and later

MX910, MX911, MX912	LW90.MG.P205 and previous	LW90.MG.P206 and later
XM9145, XM9155, XM9165	LW90.MG.P205 and previous	LW90.MG.P206 and later
MX6500e	LW90.JD.P205 and previous	LW90.JD.P206 and later
CS510, CS517	LW90.VY4.P205 and previous	LW90.VY4.P206 and later
C2132	LW90.VY4.P205 and previous	LW90.VY4.P206 and later
CX410, CX417	LW90.GM4.P205 and previous	LW90.GM4.P206 and later
XC2130	LW90.GM4.P205 and previous	LW90.GM4.P206 and later
CX510, CX517	LW90.GM7.P205 and previous	LW90.GM7.P206 and later
XC2132	LW90.GM7.P205 and previous	LW90.GM7.P206 and later
MS310, MS312, MS317, MS410	LW80.PRL.P249 and previous	LW80.PRL.P250 and later
M1140	LW80.PRL.P249 and previous	LW80.PRL.P250 and later
MX310, MX317	LW80.SB2.P249 and previous	LW80.SB2.P250 and later
XM1135	LW80.SB2.P249 and previous	LW80.SB2.P250 and later
CS310, CS317	LW80.VYL.P249 and previous	LW80.VYL.P250 and later
CS410, CS417	LW80.VY2.P249 and previous	LW80.VY2.P250 and later
CX310, CX317	LW80.GM2.P249 and previous	LW80.GM2.P250 and later
C746	LHS60.CM2.P763 and previous	LHS60.CM2.P764 and later
C748, CS748	LHS60.CM4.P763 and previous	LHS60.CM4.P764 and later
C792, CS796	LHS60.HC.P763 and previous	LHS60.HC.P764 and later
C925	LHS60.HV.P763 and previous	LHS60.HV.P764 and later
C950	LHS60.TP.P763 and previous	LHS60.TP.P764 and later
X548, XS548	LHS60.VK.P763 and previous	LHS60.VK.P764 and later
X746, X748, XS748	LHS60.NY.P763 and previous	LHS60.NY.P764 and later
X792, XS795, XS796, XS798	LHS60.MR.P763 and previous	LHS60.MR.P764 and later
X925, XS925	LHS60.HK.P763 and previous	LHS60.HK.P764 and later
X950, X952, X954, XS950, XS955	LHS60.TQ.P763 and previous	LHS60.TQ.P764 and later
6500e	LHS60.JR.P763 and previous	LHS60.JR.P764 and later

## ***Obtaining Updated Software***

To obtain firmware that resolves this issue or if you have special code, please contact Lexmark's Technical Support Center at <http://support.lexmark.com> to find your local support center.

## ***Workarounds***

Lexmark recommends a firmware update if your device has affected firmware.

## ***Exploitation and Public Announcements***

Lexmark is not aware of any malicious use against Lexmark products of the vulnerability described in this advisory.

Lexmark would like to thank the following people working with Trend Micro's Zero Day Initiative (ZDI) for bringing this issue to our attention:

Rick de Jager of team PHPHooligans  
Carlo Meijer of team PHPHooligans  
Jonathan Jagt of team PHPHooligans

### ***Status of this Notice:***

THIS DOCUMENT IS PROVIDED ON AN "AS IS" BASIS AND IS PROVIDED WITHOUT ANY EXPRESS OR IMPLIED GUARANTEE OR WARRANTY WHATSOEVER, INCLUDING BUT NOT LIMITED TO THE WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR USE OR PURPOSE. LEXMARK RESERVES THE RIGHT TO CHANGE OR UPDATE THIS DOCUMENT AT ANY TIME.

### ***Distribution***

This advisory is posted on Lexmark's web site at <http://support.lexmark.com/alerts>  
Future updates to this document will be posted on Lexmark's web site at the same location.

### ***Revision History***

<u>Revision</u>	<u>Date</u>	<u>Reason</u>
1.0	05 January 2024	Initial Public Release
1.1	22 January 2024	Fixed typos in Affected Products